LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	_ Located In:	Corner Code #		
(County)				
1. Public Land Survey	T 48N R 33V	V K4		127 127
2. Property Controlling in Section	S T R R S 12 T 48N R 33V		2	
3. Miscellaneous Property in Sec.	S T R S T R		**************************************	
4. Lot No. , Recorded Plat			Register of Deeds Stamp & File No	ımber
5. Private Claims			ABCDEFGHI	JKLM
	K4	06/13/2012	z -	- _ _
ı, Stephan J. Szyszkoski , i		0044040040	3	Ili
		06/13/2012 do hereby s		
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2				1112
above were in conformance with regulations and rules therefore as required in the current manual of survey 5				
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6				
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7				
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			lished, 8 19 20 21 22	23 24
Total Control of Monante Meday 1 dedy	ered, round as expressed below:		9	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			10 30 29 28 27	26 25
			11	
on this certificate.			12-31-32-33-34	
	2 8			3336
			<u> </u>	

A. Description of original monument and accessories and/or subsequent restoration:

(K4) Quarter corner common to Sections 11 and 12. 1975 - Reestablished by K.L.Sackett RLS midway and on the Section line between Section corners north and south. Set 1"IDx24" I.pipe with 4" alum. cap. 10" Y.Birch N49E 30.3', 8" Sugar S40W 18.6', 14" Sugar S32E 20.7'.

(10-Sec. 12) South 1/16 corner between Sections 11 and 12. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K4) Found the 1975 monument in good condition, substantially at the record position, and at record bearing and distance from the 1975 witnesses. The NBT Y.Birch N49E and Sugar S32E are both standing dead stubs. The NBT Sugar S40W is in good condition. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

(10-Sec. 12) Established the position for the corner midway and on the Section line between Section corner 1321.51' south and Quarter corner 1321.51' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K4) Fd. 1"ID I.pipe w/4" alum. State of MI cap Set measuring nail with MDNR tag in the side of: 12" Sugar S44W 19.0' old blazes 1975 NBT 17" Sugar N41W 30.25' mrkd "1/4S NBT" 4" Maple N46E 31.95' do 5" Cherry S71E 11.75' do Set sq'd cedar post adjacent. Bearings are magnetic.

(10) Set 1"IDx32" I.pipe with 4" alum. MDNR cap made firm in a mound of rock. Set measuring nail with MDNR tag in the side of: 11" Spruce N14E 14.4' mrkd "1/16S BT" 4" Y.Birch S65E 22.8' do 11" Maple S08E 23.15' do 5" Hemlock S67W 32.85' do Set sq'd cedar post adjacent. Bearings are magnetic.

Surveyor's Michigan License No. 33986 For the Michigan Department of Natural Resources, Forest Resources Division

Date 09/04/2012

LAND SURVEYOR

STEPHAN J SZYSZKOSKI

33986

16921

FORM APPROVED BY MICHIGAN STATE BOARD OF PRO SIONAL MUNICESOR

lay 14, 1975 Revised Jan., 1983 Rervised Oct., 1995