

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 49N R 32W	L5
	T 49N R 32W	J1
2. Property Controlling in Section	T R	
	T R	
	T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Stephan J. Szyszkoski, in a field survey on L5 05/17/2011 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(L5) Quarter corner common to Sections 12-13. 1852 - Established by Guy Carleton Deputy Surveyor on  
the Section line between Section corners 40.105 chains east and west. Set post. Sugar 20" S58W 38  
links, Sugar 16" N05E 18 links. 1941 - Corner recovered by N.T.Thompson RLS who found Sugar BT N05E,  
with scribing visible. His notes do not state a new monument but he describes two NBTs: Y.Birch 8"  
N10W 29.6', and Y.Birch 12" S51W 20'.

(J1) Quarter corner common to Section 2 T49N-R32W and Section 35 T50N-R32W. 1946 - Established by  
Wm.A.Burt Deputy Surveyor midway and on the Township line between Section corners 40.00 chains east  
and west. Set Y.Birch post. Sugar 10" N28E 7 links, Elm 10" N63W 26 links. Found no subsequent  
record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(L5) Found a 1"ID iron pipe projected 13" a.g. at record bearing and distance from the Thompson NBTs:  
Y.Birch N05W 29.6' in good condition, Y.Birch S51W 20' a stump in an advanced stage of decay, and at  
record bearing and distance from the OBT Sugar N05E 18 links, now a stump hole. Accepted the pipe as  
a careful and faithful perpetuation of the position of the original corner.

(J1) The original post and accessories were not recovered. Found no acceptable evidence of the  
position of the original corner on the ground. Reestablished the position for the corner midway and  
on the Township line between Section corners 2632.84' east and west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L5) Found 1"ID iron pipe projecting 13" a.g.  
Placed plastic cap "Mich DNR PS33986" in pipe.  
Set measuring nail with MDNR tag in the side of:  
13" Y.Birch N05W 29.75' old blazes 1941 NBT  
10" Y.Birch S68E 7.25' mrkd "1/4S NBT"  
9" Sugar S32W 15.3' do  
5" Y.Birch N64W 5.85' do  
Set sq'd cedar post adjacent.  
Bearings are magnetic.

(J1) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
10" Sugar N05E 7.9' mrkd "1/4S NBT"  
6" Sugar S84E 29.0' do  
9" Y.Birch S29W 27.5' do  
7" Sugar S87W 28.55' do  
Set sq'd Cedar post adjacent.  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 07/27/2011

For the Michigan Department of Natural Resources, Forest Management Division

