LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

| Surveyor's Name: | Stephan J. Szyszkoski | | Survey Date: | See below | | | | |
|--|---|---|--|-----------|--|---------------------|------------------------------|----------|
| For corner(s) in: | Baraga | Cour | nty A B | CDF | FGH | 1 1 1 | | _ |
| Original Public Lar a. S S S S Property Corner b. S 20 S S S S | T 49N R 32W T R T R T R T R T R T R T R T R T R T R | Corner Code E8 (GCDB 300340) 1/16 Corner Code 13 (GCDB 260320) | 1 2 6 3 4 7 5 6 18 7 8 19 9 9 10 30 11 12 31 | 5 | 4 3 9 10 16 15 21 22 28 27 | 2 11 14 23 | - 12 - 13 - 24 - 25 | 9 10 11 |
| Part A. Corner History | | | 13 A B | C D E | 33 - 34 F G H | 35 I J K | 36 < L N | 12 13 |

- a.) Quarter corner common to Sections 20 and 21. 1852 Established by Guy Carleton, Deputy, midway and on the Section line between Section corners 40.06 chains north and south. Set post. Spruce 6" N37°W (no distance), Spruce 8" N88°E (no distance). 1993 R.W.Crampton, PS noted the corner as being marked with a 1/2" iron pipe (found) in 1993 and states the following witnesses: 6" Fir N23°W 20.93', 9" Maple N70°E 31.97', 7" Maple S34°E 20.68', 8" Fir S58°W 28.05'
- b.) Southeast 1/16 corner, Section 20. Established in 1993 by R.W.Crampton RLS at the intersection of 1/16 lines.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

- a.) July 20, 2017. The original post and accessories were not recovered. Found a 1/2" ID Iron pipe, projecting 3 ft. above ground, loosely set, and at record bearing and distance from all four of the 1993 witnesses. The Fir S58°W is standing dead, the others are in good condition. Accepted the 1/2" I.pipe as the best available evidence of the position of the corner and replaced it with a new monument as described below.
- b.) July 26, 2017. Found a 3/4" ID Iron pipe with plastic cap "LLS 24591" in good condition. Did not find any witnesses. I note that the position for this corner is about 4' west of that which might be determined by a regular subdivision using the 1999 position for corner 1/4 corner D7. I accepted the monument as a careful and faithful determination of the position of the corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

a.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap at the position of the found 1/2" iron pipe.
Set measuring nail with MDNR tag in the side of:
7" Balsam N23°W 21.2' old blaze (1993 NBT)
18" Cedar S15°W 3.35'w/old marks. Mrkd "1/4S NBT"
11" Maple N71°E 32.4' to exist. nail/washer (1993)

8" Maple S37°E 21.0' do do

Squared a 7" Balsam with Champion poster N23W 2.1' to C/L.

b.) Found 3/4" ID I.pipe with plas. cap 24591. Set measuring nail with MDNR tag in the side of:

6" Sugar N16°E 15.1' mrkd "1/16S BT" 3" Sugar S85°E 11.7' do

12" Y.Birch S44°E 9.05' do 5" Sugar S64°W 4.85' do

Set sq'd fir post adjacent. E= 7898156.569 N= 205575.908

E= 7898549.280 N= 205979.930

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00

Coord. Ref.=NGS PID RL0041: N=210246.994 m. E=7895426.985 m.

10/04/2017

Professional Surveyor's License No.:

33986

page 1 of 1

Prepared By:

S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

