

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 49N R 34W	H7
	T 49N R 34W	I7
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 11/29/12 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(H7) **Quarter corner common to Sections 15 and 22.** 1972 - Remonumented by A.O.Enger RLS at the position of
a squared post which he found set midway and on line between Section corners 39.749 chains east and
west. Set 1"IDx36" I.pipe with 4" aluminum cap. J.Pine 7" S53W 41.3', J.Pine 8" N73W 88.7'.

(I7) **Corner common to Sections 14-15-22-23.** 1971 - A.O.Enger RLS set 1"IDx36" I.pipe at a position he
found monumented with a 1"ID I.pipe and squared post probably set by Ford Forestry Center personnel.
He determined that the position had been established by double proportionate measurement to the
original record and accepted same. New BTs: J.Pine 7" S59W 9.5', J.Pine 7" N51W 17.6', J.Pine 6"
N42E 11.9', J.Pine 7" S53E 22.7'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(H7) Found the 1972 monument in good condition and at record bearing and distance from the 1972
witnesses, both dead and down. The monument is substantially at the record position, midway and on
line between Section corners and I accept same as the best available evidence of the position of the
original corner.

(I7) Found the 1971 monument in good condition. The 1971 NBTs were not recovered. Checked the
position of the corner with respect to Quarter corner H7 and Section corner G7 and found it to be in
accord with the record. Accepted the monument as a careful and faithful reestablishment of the
position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(H7) Found 1"ID I.pipe with 4" alum. MI Dept of
Conservation cap. Set measuring nail with MDNR tag
in the side of:
6" J.Pine N05°W 63.0' mrkd "1/4S NBT"
4" Spruce N54°E 39.0' do
8" J.Pine S01°E 66.4' do
6" J.Pine West 50.4' do
3" sq'd and scribed post N08W 1.35'
E=7881893.507 N=207080.466

(I7) Found 1"ID I.pipe with 4" alum. MI Dept. of
Conservation cap. Set measuring nail with MDNR
tag in the side of:
5" J.Pine N20°E 8.6' mrkd "S14 NBT"
5" J.Pine S77°E 10.55' "S23 NBT"
5" J.Pine S78°W 14.25' "S22 NBT"
6" J.Pine N43°W 12.1' "S15 NBT"
Set sq'd cedar post adjacent.
E=7882693.011 N=207066.489

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 03/13/2013

For the Michigan Department of Natural Resources, Forest Resources Division

