

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 49N R 34W	C9
	T R	
	T R	
2. Property Controlling in Section	S 29 T 49N R 34W	5
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		6		5		4		3		2		1
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 10/17/12 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established,  
monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C9) **Corner common to Sections 19-20-29-30.** 1958 - Billy D. Buckler RLS reestablished the position for  
the corner by single proportionate measurement between Section corners 1 mile north and 2 miles  
south. No original evidence found. Set 1" pipe with 4" brass cap. 8" J.Pine N60W 16 links, 8"  
J.Pine N73E 24 links, 7" J.Pine South 04 links. 1999 - The undersigned found the 1958 monument bent  
over but with the base of the monument straight and apparently at the 1958 position, at substantial  
record bearing and distance from the J.Pine N60W 16 links. The remaining NBTs are dead, down, and  
have been moved from their original positions. The monument was straightened to vertical in 1999  
and the following NBTs were taken: 4" J.Pine N63E 14.0', 6" J.Pine S29E 26.0' 8" J.Pine S30W 85.8'  
(measurements to notch).

(5) **North 1/16 corner of Section 29.** Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C9) Found the 1958 monument in good condition and at record bearing and distance from the 1999  
NBTs. The J.Pine S29E 26.0' was found bearing S29W and is now dead. The 1958 NBT 8" J.Pine N55W is  
standing dead at record bearing and distance. I note that the 1958 survey is characterized by  
rather loose measurements. This monument is situated N13E 33.9' from the position intended in 1958.  
Given that the monument is of long standing and has been used on subsequent surveys, I accept it as  
marking the position for the corner.

(5) Established the position for the corner midway and on a straight line between Quarter corner D9  
and Center of Section 29 1304.55' north and south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C9) Found 1" ID I.pipe with 4" brass MI Dept. of  
Conservation cap. Set measuring nail with MDNR tag  
in the side of:  
9" J.Pine N63°E 14.3' old scribing 1999 NBT  
9" J.Pine S29°W 85.95' do do  
4" J.Pine S03°E 21.25' mrkd "S29 NBT"  
7" J.Pine S85°W 7.75' "S30 NBT"  
Set sq'd J.Pine post adjacent.  
E=7877835.152 N=205578.160

(5) Set 1" IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
6" J.Pine N08°W 38.2' mrkd "1/16S BT"  
4" J.Pine S79°E 3.9' do  
4" J.Pine S03°W 4.4' do  
5" J.Pine N46°W 5.75' do  
Set 4"x4" treated wood post adjacent.  
E=7878621.828 N=205164.077

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 03/13/2013

For the Michigan Department of Natural Resources, Forest Resources Division

