

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 28 T 49N R 34W	11
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 12/13/12 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Southwest 1/16 corner, Section 28, being also the NW corner of Government Lot 4. 1975 - Established by K.L.Sackett
RLS. Set 1"IDx36" I.pipe with 4" alum. cap. 6" Spruce N62W 11.7', 8" Spruce N75E 35.6'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found the 1975 monument in good condition and at record bearing and distance from the 1975 BT Spruce
N75E 35.6', in good condition with overgrown blazes. The position of the monument was found to be
substantially at the prescribed position for the SW1/16 corner for a regular section - at the
intersection of 1/16 lines. 1/16 corner #10 is a calculated position midway between Section corner
E11 and Quarter corner E10, and 1/16 corners #8, #12, #15 are monumented and of record. I accepted
the monument as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 1"ID I.pipe with 4" alum. State of Michigan cap.
The monument is set flush with the ground surface.
Set measuring nail with MDNR tag in the side of:
12" Spruce N80°E 35.75' old blazes (1975 BT)
8" Spruce S10°W 18.45' mrkd "1/16S BT"
8" Oak S87°W 18.65' do
6" Maple N50°E 6.75' do
Set sq'd cedar post adjacent.
E=7879798.484 N=204333.292



Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Signed by Stephan J. Szyszkoski Date 03/13/2013
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Revised Oct., 1995