

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 49N R 34W T 49N R 34W T R	E13 F11
2. Property Controlling in Section	S T R S T R S T R	
3. Miscellaneous Property in Sec.	S T R S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 12/11/12 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E13) **Corner common to Sections 32-33 T49N-R34W and Section 4-5 T48N-R34W.** 1958 - Remonumented by Billy D.
Buckler RLS from W.Pine bearing tree S55E 20 links, down and rotted, faces and notch visible. Set
1" iron pipe with 4" brass cap. W.Pine 10" S10E 17 links, W.Pine 10" N57W 90 links, R.Pine 10" N06E
194 links. The record, dated 1959, states the corner was set in 1948, but this is surely a
typographical error and is probably meant to be 1958.

(F11) **Quarter corner common to Sections 28-33.** 1975 - Remonumented by K.L.Sackett RLS from the remains of
the two original bearing trees. Set 1"IDx36" iron pipe with 4" aluminum cap. 7" J.Pine N54E 71.4',
7" J.Pine N45E 64.5'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E13) Found the 1958 monument in good condition and at record bearing and distance from the 1958 NBT
W.Pine S10E 17 links, now a stump. The other NBTs were not recovered. Accepted the monument as a
careful and faithful perpetuation of the position of the original corner.

(F11) Found the 1975 monument in good condition and at record bearing and distance from the 1975 NBT
J.Pine N45E 64.5', in good condition with scribing visible. Accepted the monument as a careful and
faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E13) Found 1"ID I.pipe with 4" brass MI Dept. of
Conservation cap. Set measuring nail with MDNR tag
in the side of:
5" W.Pine N15°E 29.15' mrkd "S33 NBT"
5" Balsam N78°E 35.6' do
9" W.Birch S73°E 39.1' "S4 NBT"
4" Maple S30°E 11.65' do
Fd. U-shaped metal fence post S66E 0.7'
E=7879343.191 N=202338.882

(F11) Found 1"ID I.pipe with 4" alum. State of
Michigan cap. Set measuring nail with MDNR tag in
the side of:
11" J.Pine N49°E 64.8' old marks (1975 NBT)
7" J.Pine N85°E 64.0' mrkd "1/4S NBT"
15" R.Pine S43°E 74.2' do
5" J.Pine S09°W 41.25' do
Fd. U-shaped metal fence post N11E 1.0'
E=7880191.625 N=203922.182

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 03/13/2013

For the Michigan Department of Natural Resources, Forest Resources Division

