

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 49N R 34W	E10
	T R	
	T R	
2. Property Controlling in Section	S 29 T 49N R 34W	D10
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on E10 11/20/12 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D10) Center of Section 29. Not previously monumented.

(E10) Quarter corner common to Sections 28 and 29. 1959 - Billy D. Buckler RLS reestablished the position for the corner at record distance from Section corner to north and on line between Section corner north and meander corner on south side of Big Lake. Set 1" pipe with 4" brass cap. 7" J.Pine S41W 23 links, 9" J.Pine S55E 36 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D10) Established the position for the corner at the intersection of straight lines connecting opposite 1/4 corners.

(E10) Found the 1959 monument in good condition, substantially at the record position, and at record bearing and distance from the 1959 NBT J.Pine S41W 23 links, now a standing dead stub. The NBT J.Pine S55E was not recovered. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D10) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:  
4" Oak S87°W 35.4' mrkd "C1/4 BT"  
5" J.Pine S19°W 24.7' do  
Power Pole #91-22607 40C5 S31°E 35.9'  
T-fence post marking Lots 30|29 N12°E 57.0'  
4"x4" treated wood post adjacent.  
E=7878611.915 N=204766.625

(E10) Found 1"ID I.pipe with 4" brass MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:  
5" R.Pine East 28.75' mrkd "1/4S NBT"  
5" Spruce S39°E 8.05' do  
9" R.Pine S40°W 16.65' do  
9" J.Pine S73°W 54.8' do  
Set sq'd Cedar post adjacent.  
E=7879408.741 N=204751.547

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 03/13/2013

For the Michigan Department of Natural Resources, Forest Resources Division

