

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	Located In:	Corner Code #
1. Public Land Survey	T 50N R 34W	I7 (GCDB 500400)
	T 50N R 34W	I5 (GCDB 500500)
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on I7 11/04/15 I5 12/01/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I7) Corner to Sections 14-15-22-23. 1849 - Established by Wm. Burt, Deputy. Set Hemlock post. Hemlock 14" N28°W 19 links, Y. Birch 12" S20°E 17 links. 1854 - Examiner A.B. Wood finds the OBTs: Y. Birch 14" S23°E 18 links, Hemlock 16" N26°W 21 links. 1976 - A.O. Enger RLS remonumented the corner at the intersection of true line between G7 and K7 with true line between I9 and I3.

(I5) Corner common to Sections 10-11-14-15. 1849 Established by Wm. Burt, Deputy. Set Hemlock post on west side of a very steep ridge...200 ft. in height. Hemlock 12" N68°W 18 links, Hemlock 10" S54°E 22 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I7) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Determined that a blunder in the 1976 E-W field measurements by Mr. Enger resulted in his monument being placed 134' east of the position he intended. This blunder also improperly influenced his conclusion as to the relative reliability of the N-S directions over the E-W distances (from his LCRC for G7), leading him to employ the stated method for reestablishing this corner. I did not accept the 1976 monument nor the 1976 method and reestablished the position for the corner by double proportionate measurement to the original record between monumented and recorded Section corners 10490.81' north, 5245.39' south, 5256.25' west, and 5264.05' east. Destroyed the 1976 monument.

(I5) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner by double proportionate measurement to the original record between Section corner 5245.59' north, 10486.91' east, 10490.62' south, and 5222.54' west. The position falls on the west side of a steep ridge, in accord with the description in the original record.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I7) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:  
4" Sugar N53°E 11.65' mrkd "S14 NBT"  
7" Maple S62°E 11.7' "S23 NBT"  
13" Maple S48°W 16.85' "S22 NBT"  
7" Y. Birch N42°W 9.4' "S15 NBT"  
Set sq'd cedar post adjacent.  
E= 7882906.647 N= 216672.838

(I5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:  
10" Poplar N29°W 7.85' mrkd "S10 NBT"  
5" Balsam S61°W 18.6' "S15 NBT"  
3" Balsam S38°E 6.25' "S14 NBT"  
8" Poplar N75°E 11.7' "S11 NBT"  
Set sq'd cedar post adjacent.  
E= 7882934.415 N= 218271.188

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.  
Coord. Ref.=NGS PID D08499: N= 221257.621 m. E= 7884435.168 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 01/21/2016

For the Michigan Department of Natural Resources, Forest Resources Division

