

# SURVEY & REMONUMENTATION

MAY 05 1997

## COMMISSIONED LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Baraga  
(County)

Located In:

Corner Code #

- |   |                           |            |
|---|---------------------------|------------|
| 1. Public Land Survey                   | T <u>51N</u> R <u>33W</u> | <u>C-7</u> |
|   | T _____ R _____           | _____      |
|   | T _____ R _____           | _____      |
|   | T _____ R _____           | _____      |
| 2. Property Controlling<br>in Section   | S _____ T _____ R _____   | _____      |
|   | S _____ T _____ R _____   | _____      |
| 3. Miscellaneous<br>Property in Section | S _____ T _____ R _____   | _____      |
|   | S _____ T _____ R _____   | _____      |

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

RECEIVED FOR RECORD THIS 30TH DAY  
OF JULY 1996 AT 10:30 A.M. AND  
RECORDED IN LIBER 4 OF LAND CORNER  
RECORDATION RECORDS ON PAGES  
635 - 636.

*Heidi J. Schillard*  
BARAGA COUNTY REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Michael Mileski, in a field survey on July, 19 96,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found  
as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

C-7; Section Corner common to Sections 17, 18, 19, and 20, T51N, R33W;

See back of form.

APPROVED LAND CORNER  
P.A. 345 OF 1990  
Baraga County

*7/10/96*  
7-10-96

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-7; Section Corner common to Sections 17, 18, 19, and 20, T51N, R33W;

Recovered the BLM monument and all accessories as described in Part A. Alongside of  
the monument is a 4" x 4" x 18" wood post having a notch in the middle. I left the BLM  
monument in place and stamped the cap "PA 345 1996". Accepted as the best  
available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-7; Section Corner common to Sections 17, 18, 19, and 10, T51N, R33W;

See back of form.



Signed by *Michael Mileski*

Date 13 July 1996

Surveyor's Michigan License No. 39091

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983

A. Description of original monument and accessories and/or subsequent restoration:

C-7; Section Corner common to Sections, 17, 18, 19, and 20, T51N, R33W;

Originally established during U.S. Survey conducted by Harvey Mellen, D.S. in 1845 and monumented with a hemlock post witnessed by a

Cedar 12 S56°E 25 lks. and a Cedar 12 N43°W 20 lks.

During the course of a survey conducted by Stephen Douglas of the Bureau of Land Management from 10 May 1984 to 10 November 1984 and approved 23 September 1985, "the sharpened tip of a wooden post, 3½ ins. sq., firmly set, 6 ins. below the surface, lying alongside is the decayed wooden post, 3½ ins. sq., 3 ft. long, with no mks. visible" was recovered and accepted. The BLM field notes state that there is no remaining evidence of the original corner.

The BLM remonumented the corner with a 2½" x 30" aluminum pipe with cap stamped as to location and noted the following new bearing trees:

Maple 8 N20°E 100 lks. (66.00')

Found red maple presently alive and 11" in dia. having a mostly open lower blaze with scribing visible.

Set 7" spike E/side Measured N17°E 66.00'

Sugar 12 S18°E 37½ lks. (24.75')

Presently alive and 16" in dia. having a mostly open lower blaze with scribing evident.

Set 7" spike E/side Measured S23°E 24.46'

Cedar 15 S60°W 102 lks. (67.32')

Presently alive and 18" in dia. having an open lower blaze with scribing evident.

Set 7" spike NW/side Measured S53°W 67.32'

Sugar 20 N36°W 69 lks. (45.54')

Presently alive and 28" in dia. having a mostly open lower blaze with scribing visible.

Set 7" spike E/side Measured N38°W 45.54'

C. Description of monument for corner and accessories established to perpetuate locating the position:

C-7; Section Corner common to Sections 17, 18, 19, and 20, T51N, R33W;

Found a 2½" dia. aluminum pipe with 3" aluminum cap appropriately stamped as to location as set by the BLM in 1984.

Set 7" spike E/side 11" Sugar Maple N21°W 19.54'

Set 7" spike N/side 16" Sugar Maple S68°E 66.37'

Location Post South 1.0'

All of the above new bearing trees are marked with upper and lower blazes, scribed "NBT", and painted red.

The following new bearing trees were established by the BLM in 1984. The condition of each is described in Part A.

Set 7" spike E/side 11" Red Maple N17°E 66.00'

Set 7" spike E/side 16" Sugar Maple S23°E 24.46'

Set 7" spike NW/side 18" Cedar S53°W 67.32'

Set 7" spike E/side 28" Sugar Maple N38°W 45.54'

SURVEY &  
REMONUMENTATION

The above BLM new bearing trees were painted red.

MAY 05 1997