

# SURVEY & REMONUMENTATION

MAY 05 1997

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

COMMISSION

(County)

Located In:

Corner Code #

1. Public Land Survey

T 51N R 33W

C-8

T R

T R

T R

T R

2. Property Controlling in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Section

S T R

4. Lot No. , Recorded Plat

5. Private Claims

RECEIVED FOR RECORD THIS 30TH DAY OF JULY 1996 AT 10:30 A.M. AND RECORDED IN LIBER 4 OF LAND CORNER RECORDATION RECORDS ON PAGES 637 - 638.

BARAGA COUNTY REGISTER OF DEEDS

Register of Deeds Stamp & File Number

Michael Mileski

July

19 96

I, Michael Mileski, in a field survey on July 19 96, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-8; One-quarter Corner common to Sections 19 and 20, T51N, R33W;

See back of form.

APPROVED LAND CORNER  
P.A. 345 OF 1990  
Baraga County

7-10-96

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-8; One-quarter Corner common to Sections 19 and 20, T51N, R33W;

Recovered the BLM monument and all accessories as described in Part A. Alongside of the monument is a 3" squared old wood post projecting 18 inches above ground. From this monument I found a hemlock stump hole at S23°E a distance of 26 lks. and a stump hole at N83°W a distance of 27 lks. as stated by the BLM. I left the BLM monument in place and stamped the cap "PA 345 1996". Accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-8; One-quarter Corner common to Sections 19 and 20, T51N, R33W;

See back of form.



Signed by

Date

13 July 1996

Surveyor's Michigan License No. 39091

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983

A. Description of original monument and accessories and/or subsequent restoration:

C-8; One-quarter Corner common to Sections 19 and 20, T51N, R33W;

Originally established during U.S. Survey conducted by Harvey Mellen, D.S. in 1845 and monumented with a maple post witnessed by a

Hemlock 12 S23°E 26 lks. and a Spruce 14 N83°W 27 lks.

During the course of a survey conducted by Stephen Douglas of the Bureau of Land Management from 10 May 1984 to 10 November 1984 and approved 23 September 1985, a 4" squared wood post was recovered and found to be in agreement with the remains of the U.S. bearing trees. Specifically, the BLM field notes state that from the wood post monument " a hemlock stump hole, bears S23°E, 26 lks. dist. " and " a stump hole, bears N83°W, 27 lks. dist. ". The BLM remonumented the corner with a 2½" x 30" aluminum pipe with cap stamped as to location and noted the following new bearing trees:

Maple 8 N74°E 26 lks. (17.16')

Found red maple presently alive and 12" in dia. having a mostly open lower blaze with scribing evident.

Set 7" spike N/side Measured N67°E 17.16'

Maple 10 N52°W 65½ lks. (43.23')

Found red maple presently alive and 16" in dia. having a partially open lower blaze with scribing evident.

Set 7" spike SW/side Measured N60°W 42.76'

C. Description of monument for corner and accessories established to perpetuate locating the position:

C-8; One-quarter Corner common to Sections 19 and 20, T51N, R33W;

Found a 2½" dia. aluminum pipe with 3" aluminum cap appropriately stamped as to location as set by the BLM in 1984.

Set 7" spike	NE/side	13" Red Maple	S45°E	33.45'
Set 7" spike	SE/side	10" Sugar Maple	S57°W	62.91'
Set 7" spike	E/side	11" Sugar Maple	N10°W	13.20'
		Location Post	South	1.0'

All of the above new bearing trees are marked with upper and lower blazes, scribed "NBT", and painted red.

The following new bearing trees were established by the BLM in 1984. The condition of each is described in Part A.

Set 7" spike	N/side	12" Red Maple	N67°E	17.16'
Set 7" spike	SW/side	16" Red Maple	N60°W	42.76'

The above BLM new bearing trees were painted red.

SURVEY &  
REMONUMENTATION

MAY 05 1997

COMMISSION