

BARRY COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF BARRY
RECEIVED FOR RECORD

DEC 14 8 54 AM '93

Sandy Schondelmayer
REGISTER OF DEEDS

002167

Register of Deeds Stamp & File Number

BARRY

Located In: Corner Code ##

T 1N R 9W A-2.8

T 1N R 10W M-2.8

WITNESS CORNER TO MEANDER POST
ON TOWNSHIP LINE BETWEEN
BARRY AND PRAIRIEVILLE

S T R
S T R
S T R

Public Land Survey

Property Controlling
in Section
Miscellaneous
Property in Sec.

Lot No. , Recorded Plat

Private Claims

BRIAN REYNOLDS in a field survey on JUL 19 93

hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the present manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as pressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

- G.L.O. : N. FROM SE. CORNER SECTION 1 - T1N - R10W - 7.87chains, LEAVE LAKE, SET POST: W. OAK - 7 - N21E - 89; Y. OAK - 0.5 - S60E - 84. (PG. 6, ORIGINAL GOV'T NOTES).
- CRESSEY (OCT. - NOV. 1884) (PRAIRIEVILLE RESURVEY) N. FROM SE. CORNER SECTION 1 - T1N - R10W - 7.95 chains, LEAVE LAKE.
- PLAT OF "HIGHLAND POINT RESORT" (LIBER 1, PAGE 43) INDICATES MEANDER POST (COBB, 1894). THIS PLAT WAS SUPERSEDED BY PLAT OF "STONY POINT" (LIBER 2, PAGE 6) WHICH ALSO INDICATES MEANDER POST (GLEN C. WHEATON, 1913).
- WAYLAND INGERSOLL (NOV. - DEC. 1967) (SURVEY OF "BLACKMAN" PROPERTY) SET WELL POINT FOR SE. COR. SEC. 1 - T1N - R10W. NO MEANDER POST SET.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- CHECKED FOR MEANDER CORNER AS STATED BY G.L.O. , CRESSEY, COBB, AND WHEATON. NO CORNER EVIDENCE FOUND.
- GIVEN PRESENT LEVEL OF CROOKED LAKE BOTH LAKE EDGE CORNERS WOULD MOST LIKELY BE UNDER WATER.
- SE. SECTION CORNER SEC. 1 - T1N - R10W IS UNDER WATER.
- RANGE LINE WAS REESTABLISHED FROM PLAT OF "STONY POINT". REMON. IRON SET ON RANGE LINE AT NORTH SHORE OF CROOKED LAKE.

SURVEY &
REMONUMENTATION

APR 05 1994

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- SET WITNESS CORNER TO MEANDER POST: BARRY Co. REMONUMENTATION MON.
- 1782.10' SOUTH OF W1/4 POST SEC. 6 - T1N - R10W
- N&T - SW. SIDE - 24" WILLOW - N64W - 57.60'
- N&T - E. SIDE - 18" OAK - N6W - 51.70'
- N&T - E. SIDE - 30" OAK - N22E - 50.68'
- N&T - W. SIDE - 16" MAPLE - 70.10'
- ORANGE CAPPED 1/2" REROD (TRAV. PT.) - N73-48-56W - 65.87'
- +/- 2' - NORTH OF SHORE, CROOKED LAKE



Witnessed by [Signature] Surveyor's Michigan License No. 31602

Date DECEMBER 10, 1993