

MAY 2 1997

COMMISSION

BARRY COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970STATE OF MICHIGAN
COUNTY OF BARRY
RECEIVED FOR RECORD

DEC 14 8 54 AM '93

For corners in

BARRY

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 1N R 9W A-2.8

T 1N R 10W M-2.8

WITNESS CORNER TO MEANDER POST

ON TOWNSHIP LINE BETWEEN

S BARRY AND R PRAIRIEVILLE

2. Property Controlling
in Section

3. Miscellaneous

Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Sandy Schondelmayer

REGISTER OF DEEDS

002167

Register of Deeds Stamp & File Number

I, BRIAN REYNOLDS, in a field survey on JUL, 19 93,

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- G.L.O. : N. FROM SE. CORNER SECTION 1 - T1N - R10W - 7.87chains, LEAVE LAKE, SET POST:

W. OAK - 7 - N21E - 89; Y. OAK - 0 5 - S60E - 84. (PG. 6, ORIGINAL GOV'T NOTES).

- CRESSEY (OCT. - NOV. 1884) (PRAIRIEVILLE RESURVEY) N. FROM SE. CORNER SECTION

1-T1N-R10W - 7.95 chains, LEAVE LAKE.

- PLAT OF "HIGHLAND POINT RESORT" (LIBER 1, PAGE 43) INDICATES MEANDER POST (COBB, 1894). THIS PLAT WAS SUPERSEDED BY PLAT OF "STONY POINT"

(LIBER 2, PAGE 6) WHICH ALSO INDICATES MEANDER POST (GLEN C. WHEATON, 1913).

- WAYLAND INGERSOLL (NOV. - DEC. 1967) (SURVEY OF "BLACKMAN" PROPERTY) SET WELL POINT FOR SE. COR. SEC. 1 - T1N - R10W. NO MEANDER POST SET.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- CHECKED FOR MEANDER CORNER AS STATED BY G.L.O., CRESSEY, COBB, AND WHEATON. NO CORNER EVIDENCE FOUND.

- GIVEN PRESENT LEVEL OF CROOKED LAKE BOTH LAKE EDGE CORNERS WOULD MOST LIKELY BE UNDER WATER.

- SE. SECTION CORNER SEC. 1 - T1N - R10W IS UNDER WATER.

- RANGE LINE WAS REESTABLISHED FROM PLAT OF "STONY POINT". REMON. IRON SET ON RANGE LINE AT NORTH SHORE OF CROOKED LAKE.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- SET WITNESS CORNER TO MEANDER POST: BARRY Co. REMONUMENTATION MON.

- 1782.10' SOUTH OF W1/4 POST SEC. 6-T1N-R10W

- N&T - SW. SIDE - 24" WILLOW - N64W - 57.60'

- N&T - E. SIDE - 18" OAK - N6W - 51.70'

- N&T - E. SIDE - 30" OAK - N22E - 50.68'

- N&T - W. SIDE - 16" MAPLE - 70.10'

- ORANGE CAPPED 1/2" REROD (TRAV. PT.) - N73-48-56W - 65.87'

- +/- 2' - NORTH OF SHORE, CROOKED LAKE



Signed by

Date

DECEMBER 10, 1993

Surveyor's Michigan License No.

31602