

MAY 2 2 1987

REMONUMENTATION

BARRY COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF BARRY
RECEIVED FOR RECORD

DEC 14 8 54 AM '93

Sandy Schondelmayer
REGISTER OF DEEDS

For corners in **BARRY**
(County)

Located In: Corner Code ##

1. Public Land Survey

T 1N R 9W A-2.35
T 1N R 10W M-2.35

WITNESS CORNER TO MEANDER POST
ON TOWNSHIP LINE BETWEEN
BARRY AND PRAIRIEVILLE

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R #2

002168

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, **BRIAN REYNOLDS**, in a field survey on JUL, 19 93,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

- G.L.O. N. FROM SE. CORNER SECTION 1-T1N-R10W- 26.16 chains, SET POST ON LAKE:
- B. OAK - 32 - S63E - 72; ASPEN - 6 - S28W - 76. (PG. 6, ORIGINAL GOV'T. NOTES).
- CRESSEY (OCT. - NOV. 1884) (PRAIRIEVILLE RESURVEY) N. FROM SE. CORNER SECTION
1-T1N-R10W - 26.20 chains, S. BOUNDARY OF LAKE.
- PLAT OF "HIGHLAND POINT RESORT" (LIBER 1, PAGE 43) INDICATES MEANDER POST (COBB, 1894). THIS
PLAT WAS SUPERSEDED BY PLAT OF "STONY POINT"
(LIBER 2, PAGE 6) WHICH ALSO INDICATES MEANDER POST (GLEN C. WHEATON, 1913).
- WAYLAND INGERSOLL (NOV. - DEC. 1967) (SURVEY OF "BLACKMAN" PROPERTY) FOUND IRON ROD ON
SECTION LINE 708.82' S. OF WEST 1/4 CORNER SEC 6-T1N-R10W, NEAR EDGE OF LAKE.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- CHECKED FOR MEANDER CORNER AS STATED BY G.L.O. , CRESSEY, COBB, AND WHEATON. NO CORNER
EVIDENCE FOUND.
- LOOKED FOR IRON ROD FOUND BY WAYLAND INGERSOLL. NO EVIDENCE FOUND.
- GIVEN PRESENT LEVEL OF CROOKED LAKE BOTH LAKE EDGE CORNERS WOULD MOST LIKELY BE
UNDER WATER.
- RANGE LINE WAS REESTABLISHED FROM PLAT OF "STONY POINT". REMON. IRON SET ON RANGE LINE
AT SOUTH SHORE OF CROOKED LAKE.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- SET WITNESS CORNER TO MEANDER POST: BARRY Co. REMONUMENTATION MON.
- 732.88' SOUTH OF W1/4 POST SEC. 6-T1N-R10W
- CAPPED 1/2" IRON (LOT COR.) (L.S. #31602) - S. - 10.00'
- N. FACE - 12" MAPLE - N57E - 8.44'
- SW. FACE - 24" OAK - N73W - 6.74'
- NW. COR. HSE. # 10696 - S88E - 23.18'
- LAKE EDGE +/-10' NORTH



Signed by [Signature]
Surveyor's Michigan License No. 31602

Date NOVEMBER 4, 1993