

MAY 2 1997

BARRY COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF BARRY
RECEIVED FOR RECORD

DEC 14 8 54 AM '93

For corners in

BARRY

(County)

Located In:

Corner Code --#

1. Public Land Survey

T 1N R 9W A-2.15
T 1N R 10W M-2.15WITNESS CORNER TO MEANDER POST
ON TOWNSHIP LINE BETWEEN
S BARRY AND R PRAIRIEVILLE2. Property Controlling
in Section3. Miscellaneous
Property in Sec.S T R
S T R

#3

4. Lot No. , Recorded Plat

5. Private Claims

Sandy Schendelmayer
REGISTER OF DEEDS

002169

Register of Deeds Stamp & File Number

I, **BRIAN REYNOLDS**, in a field survey on **JUL**, 19 **93**, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- G.L.O. N. FROM SE. CORNER SECTION 1-T1N-R10W- 34.00 chains, LEAVE LAKE, SET POST: W. OAK - 7 - N21E - 89; Y. OAK - 5 - S60E - 84. (PG. 6, ORIGINAL GOV'T. NOTES).
- CRESSEY (OCT. - NOV. 1884) (PRAIRIEVILLE RESURVEY) N. FROM SE. CORNER SECTION 1-T1N-R10W - 34.50 chains, LEAVE LAKE, FOUND MEANDER POST.
- WAYLAND INGERSOLL (NOV. - DEC. 1967) (SURVEY OF "BLACKMAN" PROPERTY) SET IRON ROD ON SECTION LINE 153.54' S. OF WEST 1/4 CORNER SEC 6-T1N-R10W, NEAR EDGE OF LAKE.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- CHECKED FOR MEANDER CORNER AS STATED BY G.L.O. AND CRESSEY. NO CORNER EVIDENCE FOUND.
- LOOKED FOR IRON ROD SET BY WAYLAND INGERSOLL. NO EVIDENCE FOUND.
- GIVEN PRESENT LEVEL OF CROOKED LAKE BOTH LAKE EDGE CORNERS WOULD MOST LIKELY BE UNDER WATER.
- REMON. IRON PLACED ON RANGE LINE (AS DEFINED BY FOUND "CRESSEY" TILE AT M-2 AND PLAT OF "STONY POINT") AT NORTH SHORE OF CROOKED LAKE.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- SET WITNESS CORNER TO MEANDER POST: BARRY Co. REMONUMENTATION MON.
- 138.93' SOUTH OF W1/4 POST SEC. 6-T1N-R10W
- S. FACE - 10" OAK - N78W - 37.58'
- S. FACE - 16" OAK - N44W - 22.23'
- N. FACE - 4" MULBERRY - N63E - 76.02'
- N. FACE - 6" SYCAMORE - N83W - 21.65'
- LAKE EDGE +/- 2' SOUTH



Signed by

Date

DECEMBER 7, 1993

Surveyor's Michigan License No.

31602