| AllFIED BY THE BERRIEN COUNTY NORTH QUARTER CORNER SECTORIVEY PEER GROUP AS THE BERRIEN COUNTY REMONUM FICAL CORNER UNDER MICHIGANLAND CORNER RECORDATION C PUBLIC ACT 345 OF 1990 Filing Requirement of Act 74, Mic For corners in Located in: Corner Code # BERRIEN COUNTY PIPESTONE TWP. (F-5) N1/4 CORNER SEC.16 1. Public Land Survey T_5S R_17W F-5 T R T R T R | ERTIFICATE |
|---|--|
| 2. Property Controlling S T R | 11/02/99 111#6969 A77 CORNER \$9.00 11/02/99 111#6969 A77 A.B.C. D.E. F. G. H. STATE REMON FEE \$2.00 |
| 4. Lot No,Recorded Plat | 2 - 6 - 5 - 4 - 3 - 2 - 1 - 3 - 4 - 7 - 8 - 9 - 10 - 11 - 12 - 5 - 4 - 15 - 14 - 13 - 7 - 16 - 15 - 14 - 13 - 7 - 16 - 15 - 14 - 13 - 7 - 10 - 30 - 29 - 28 - 27 - 26 - 25 - 11 - 12 - 31 - 32 - 33 - 34 - 35 - 36 - 13 |
| NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. | RECORDER DE LA COMPANSION DE LA COMPANSI |
| A. Description of original monument and accessories and/or subsequent restoration: | DEC 2 8 1999 |
| (PLEASE SEE BACK PAGE) | SECTION |
| B. Description of corner evidence found and/or method applied in restoring or reestal Verified Corner using existing witnesses. This corner approved by the Berrien Group of Surveyors June 22 1999. | |
| C. Description of monument for corner and accessories established to perpetuate local Set Berrien County Remonumentation Monument in Mon Box Witnesses PK (set) in Power Pole S80E 229.75' Nail (fnd) in Power Pole N20W 33.54' PK (set) in Power Pole N80W 190.82' NE cor (top) of conc headwall N55W 41.37' NE " " " " S70W 41.71' Comer is accepted as a careful and faithful perpetuation of the position of the original Signed by All All All All All All All All All Al | |

LIBER 4 PAGE 174

F-5 N1/4 CORNER SEC 16 T5S,R17W

GLO April 24 1830

John Mullett

West corrected between secs 9 & 16 40.09 Set Post 1/4 Sec Cor on True Line.

Witnesses

S58F 25 W Wood 12 Sycamore12 west 24

80.18 Sec Cor

April 1890

S. Hemmingway Dept. Co. Surveyor

Survey for Clark, Robinson, Hersetter et al.

....N 1/4 Post & S1/4 Post could not be found. After strict search and due enginuity located by proportional measurements to wit; From W1/4 Post run and measured North, at 79.63 chs came Elm Tree original corner between secs 5 & 8 run and measured East setting temp 1o(?) chs at every 20.00 chs. At 120.23 came to NE Corner of sec 9 corrected West at 79.92+ chs Post, Brick and smaller stones for SE Corner. Run and Measured South Line of Sec. At 1/2 distance & on true line SET POST, BRICKS, PLOW POINT, AND BROKEN SEWER TILE FOR THE SOUTH 1/4 POST.

Oct 1972

Recorded Survey Liber937 Page 973 Southwest Surveys

Steel Ball

Witnesses

N30W 33.61' Nail in P.P.

N60W 41.69' NE Cor Conc CMP

S60W 41.63 SE Cor Conc CMP

Survey shows ½ mile distance of 2638.65' between E-5 and F-5

Misc Survey

No description of Corner

Survey shows ½ mile distanc of 2638.?? between E-5 and F-5

1980

Berrien Co. Road Commission

"Plug"

Witnesses

S80W 132.5' Ash S20E 117.7 Cherry

NE corner of headwall S60W 41.2' NE corner of headwall N60W 41.5' S80W 146.5'

18" Maple P.P.

N30W 33.6'

1/2 Mile distance between E5 and F5 = 2638.8' 1/2 Mile distance between F5 and G5 = 2645.6'

April 1980

Survey Certificate M.R. Rushlow RLS No.15191

R.R. Spike

Witnesses

PP S45W

Cherry

S45E 57.52

24" Maple

54.20' **S45E**

Dec 1981

John G. Kamer RLS No. 27449 **Survey Certificate**

41.85

Mon box (Plug)

Witnesses

Nail in PP

N20W 33.58'

P.K. Nail in Guard Post S75W 49.41'

Survey shows 1/2 mile distance of 2645.68' between F-5 & G-5

June 1999

Landmark Technologies Alan Bartlett #35988

Found plug in Mon. Box, 1.5' North of c/l Naomi

Witnesses

PK (set) in Power Pole S80E 229.75 N20W 33.54' Nail (fnd) in Power Pole

N80W 190.82^t PK (set) in Power Pole NE cor (top) of conc headwall N55W 41.37'

\$70W 41.71 NE "

DEC 2 3 1999