

SURVEY &  
REMONUMENTATION  
DEC 08 1993  
COMMISSION

11/29/93

111#2893

A33

CORNER

\$7.00

11/29/93

111#2893

A33

STATE REMON FEE \$2.00

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Berrien County Remonumentation

FOR CORNERS OF--	<u>Berrien</u> <u>COUNTY</u>	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. <u>8</u> N. S., R. <u>17</u> E. W.		<u>J-9</u>
2. PROPERTY CONTROLLING IN SECTION <u>23</u>	T. <u>8</u> N. S., R. <u>17</u> E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.		
4. LOT NO.	RECORDED PLAT		
5. PRIVATE CLAIMS			

RECORDED  
NOV 29 2 08 PM '93  
REGISTER OF DEEDS  
ST. CLAIR COUNTY, MICHIGAN

RECORDED

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Robert W. Prestine, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on OCT. 29, 1993, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

J-9 NOT SET BY GOVT. (on state line.)  
GOVT. Survey 1827 By Wm. Brookfield D.S.  
S1/4 COR.  
Sec. 23

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

J-9 Found 3/4" pipe in monument Box.  
D.M. Dreher R.L.S., R.R. SPIKE 1971  
John Kemer R.L.S. M.Box 1986  
also checks with Plat of Okoboji (recorded Plat)  
R.W. Prestine 1/2" rebar 1975

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-9 Could NOT remove 3/4" iron fd. in mon. Box  
SET Berrien Co. remonumentation cap in side  
of existing iron.  
Nail & washer in side E100. Pole  
N88°E 32.70'  
NW COR CONC. Bldg. 538°E 60.93'  
mon Box North 23.0' E STATE  
Line Rd. going east  
Indiana Sec. corner west,  
along STATE LINE 200.11'  
(4" cast iron monument)  
ratified by Peer Group 11-8-93

SIGNED BY Robert W. Prestine DATE NOV. 29-93

SURVEYOR'S MICHIGAN REGISTRATION NO. 18662

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

MICHIGAN REGISTERED LAND SURVEYOR

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

