BERRIEN COUNTY REMONUMENTATION PROGRAM

DEC	28	2	17	'55

LAND CORNER RECORDATION CERTIFICATE 2/28/93

	OOMELI ME	7011DA110	II OFILIA	OM 1 12 27 20
Filing	Requirement	of Act 74,	Mich. P.A.	1970

111#5115 CORNER A33 \$7.00

Berrien F. S. W. T. S.

Located In:

Corner Code ##

12/28/93 111#5115

111#5115 A33 STATE RENDIN FEE \$2.00

Public Land Survey

T8 S. R 17 W. T8 S. R 17 W.

_H-9_meander _I-9_meander

_₩. <u>I</u>-9_mear

T _____ R __ T ____ R __

2. Property Controlling

S ____ T ___ R ___ S ___ T ___ R ___

Register of Deeds Stamp & File Number

in Section
3. Miscellaneous

Property in Sec.

5. Private Claims ___

S ____ R _ S ___ R __ R __

_____ , Recorded Plat _

0.7

I, R.L. Harner , in a field survey on November 11, 19 83 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

H-9 Meander

Post - Thomas Love County Surveyor May 1874

3" blk. oak N. 51 3/4° W. 35 links 8" white oak S. 73° W. 70 ½ links

Iron - I & M Elec. Co. 1936 & 1984

F-9 Meander

Iron - St. Joseph County Surveyor (Indiana) 1975

H-9 Meander

Found 3/4" capped I & M iron

I-9 Meander Found 3/4" iron

SUNVEY &
REMONUMENTATION

NOV 2 1996

COMMISSION

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-9 Meander

Set concrete monument with brass cap

Nail in 30" oak East 1.58 ft.

5/8" rebar S. 45° W. 13.35 ft. 5/8" rebar N. 40° W. 13.91 ft.

Nail in 8" oak N. 2° E. 31.30 ft.

25'± West of top of bank

I-9 Meander

Set concrete monument with brass cap

Nail in 12" oak South 8.60 ft.

Nail in 16" oak S. 85° W. 29.75 ft.

Nail in $8^{\prime\prime\prime}$ oak N. $45^{\circ\prime}$ W. 21.60 ft. Nail in $12^{\prime\prime\prime}$ oak North 4.55 ft.

Top of low bank West 44.0 ft. ±

igned by:

_ Date ___December 28, 1993

urveyor's Michigan License No. 22436

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971