BERRIEN COUNTY REMONUMENTATION PROGRAM

DEC 28 2 17 PM '93

LAND CORNER RECORDATION CERTIFICATE 2/28/93

Filina	Requirement	of	Act	74.	Mich.	P.A. 1970	

111455115

For come to server of the three says

CORNER 12/28/93 111#5115

Located In:

Corner Code ##

STATE REMON FEE \$2.00

1. Public Land Survey T8 S. R 17 W. T 8_S. R 17 W. ...I-9 meande ___ R[.]___ ___ R _

2. Property Controlling

_ T ____ R _ T...... R... in Section Miscellaneous

Register of Deeds Stamp & File Number

___ , Recorded Plat __

5. Private Claims

Property in Sec.

, in a field survey on November 11, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

6 8 10 11 12

A. Description of original monument and accessories and/or subsequent restoration;

H-9 Meander

Post - Thomas Love County Surveyor May 1874

3" blk. oak N. 51 3/4° W. 35 links 8" white oak S. 73° W. 70 $\frac{1}{2}$ links Iron - I & M Elec. Co. 1936 & 1984

F-9 Meander

Iron - St. Joseph County Surveyor (Indiana) 1975

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-9 Meander

Found 3/4" capped I & M iron

I-9 Meander Found 3/4" iron

SUPVEY & REMONUMENTATION

NOV 2 1 1996

COMMISSION

Description of monument for corner and accessories established to perpetuate locating the position of the corner.

H-9 Meander

Set concrete monument with brass cap

Nail in 30" oak East 1.58 ft.

5/8" rebar S. 45° W. 13.35 ft.

5/8" rebar N. 40° W. 13.91 ft.

Nail in 8" oak N. 2° E. 31.30 ft.

25'± West of top of bank

urveyor's Michigan License No...

I-9 Meander

Set concrete monument with brass cap

Nail in 12" oak South 8.60 ft.

Nail in 16" oak S. 85° W. 29.75 ft.

Nail in 8" oak N. 45° W. 21.60 ft.

Nail in 12" oak North 4.55 ft.

Top of low bank West 44.0 ft.±

Date ___December_28, 1993___

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971