

1993

BRANCH COUNTY REMONUMENTATION CORNER  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

COMMISSION

BRANCH  
(County)

Located In:

Corner Code #

1. Public Land Survey

T6S R 6W

E 1

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

249

Register of Deeds Stamp & File Number

REGISTER OF DEEDS

93 DEC 27 AM 10:06

REC'D FOR RECORD  
STATE OF MICHIGAN  
BRANCH COUNTY

I, Edward W. Reed in a field survey on November 30, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-1 NORTHWEST CORNER OF SECTION 4, T6S, R6W, COLDWATER TWP.

1909: Cox, Surveyor - Stone, not found, does not say what he place at this corner.

1957: E.R.Reed, County Surveyor - found a badly rusted iron, which was possibly a lighting rod iron. Miner's (Surveyor) old section corner record calls this corner a "pin", replaced old ruste iron with a 5/8"x16" square head bolt iron.

1975: R.E. Burris, Surveyor - Found 5/8" square head iron and recorded in Land Corner Record #00132

1982: E.R. Reed, County Surveyor - Found 5/8" square head iron and recorded in Land Corner Record # II-0056.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" square head bolt iron as described in Land Corner Records of Burris and Reed.

Set 1/2" x 18" rebar iron with ID cap in CI-monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Rebar iron as noted above.

S 50 W 41.9', Steel corner post

N 65 W 41.73', Steel corner post

S 61 E 74.6', Telephone pole

S 70 W 43.5', Telephone pole

S 40 W 55.4', 12" Walnut

West 10.4, C/L blacktop road

And is accepted as a careful and faithful perpetuation of the position of the original corner.

Signed by Edward W. Reed

Date November 30, 1993

Surveyor's Michigan License No. 33985

