

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Chippewa Co.

2 Corners.

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY—	T. <u>41</u> N. <u>X</u> , R. <u>6</u> E. <u>X</u>	M-2, M.C. North of M-2
2. PROPERTY CONTROLLING IN SECTION—	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	
3. MISCELLANEOUS PROPERTY IN SECTION—	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, David L. Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 7-21, 1982, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- 2 East 1/4 cor. of sec. 1. Wood Post, Sugar 10", N31°W, 30 lks. & Ironwood 6", S32°W, 28 lks.
- C. Meander Corner on south side of "Dry Lake" on east line of section 1, Meander Corner North of M-2. Tamarack 18" for M.C.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- 2 Set by prop. to the original survey record betw. the Meander cor. on the south shore of Dry Lake, on the east line of sec. 1, and the SE sec. cor. of sec. 1. No sign of O&T'S.
- C. Set M.C. on the south shore of Dry Lake by fitting the meander record from the original Gov't survey to the existing Lake Shore. These are quite definite and cause the SE sec. cor. of sec. 1 (set on a straight line) to fall in the approx. center line of a N-S county road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | |
|------------------------------------------------------------------------------|-------------------------------------|
| 2 D.N.R. Monument. New Bearings: | M.C. D.N.R. Monument. New Bearings: |
| 6" Spruce, S23°E, 42.5' | Lake Shore, North, 13.0' |
| 38" W. Birch, S58°W, 41.8' (Not Marked) | 6" Cedar, N63°E, 28.4' |
| 18" Spruce, N42°W, 134.7' | 2" Tam., S78°E, 30.2' |
| Center of 3/4 YD. Pudding Stone (Conglomerate reddish colored), N47°E, 52.3' | 6" Tam., S06°W, 15.1' |
| | 6" Spruce, N67°W, 24.9' |

SIGNED BY David L. Babbitt DATE 8-3-82

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)