

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Chippewa Co.

3 Corners.

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 42 N. R. 2 E.	C-3, G-3, G-5
2. PROPERTY CONTROLLING IN SECTION	T. S. R. E.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. E.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Luckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 8-7, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:
Corners set by John Mullett, D.S. in 1845. Bearings were:

- C-3 Sec. Cor. common to Sec's. 5-6-7-8. Cedar 14", N10°E, 19 lks. & Cedar 8", S30°W, 15 lks.
- G-3 Sec. Cor. common to Sec's. 3-4-9-10. Sugar 10", N63°W, 23 lks. & Sugar 14", S79°E, 13 lks.
- G-5 Sec. Cor. common to Sec's. 9-10-15-16. Sugar 14", N53°E, 8 lks. & Birch 8", S37°W, 12 lks.

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- C-3 Placed iron pipe in intersection of roads, North, South, and East and in line with South edge of road to West. Fence line locations to North and South agree well with this location. Distance North (5290') to a corner on Highway M-48 checks with record distance.
 - G-3 This corner placed in intersection of roads in all four directions. Found no evidence of original corner.
 - G-5 This corner re-witnessed as set by unknown surveyor. Found 1" iron in center of road, in line with fences to east and west; and 29.0' from fence to West; 32.5' from fence to East.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- C-3 Placed 1 1/2" x 18" iron pipe. No witnesses.
 - G-3 Placed 1" x 24" Iron Pipe buried in road intersection. No witnesses.
 - G-5 Placed 1" Iron, driven in center of N-S road. Bearings: 12" Twin Oak, N57°W, 34.0' & 7" Hard Maple, S36°E, 53.5'.

SIGNED BY

Billy D. Luckler
Billy D. Luckler

DATE 8-3-81

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY

CHIEF OF SURVEY PARTY

DATE

APPROVED AND SIGNED BY

MICHIGAN REGISTERED LAND SURVEYOR

DATE

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____