RETO DVE A MAR S 0 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 197000 LAND CURNER

Chippewa County Remonumentation Corne 2.00 MSSR

For corners in

Located in: Corner Code # Chippewa County T44N R2W 1. Public Land Survey G-2 T R T R T R Т 2. Property Controlling R T in Section S R 3. Miscellaneous S Т R Property in Sec. S R

5 MAR 1999 2:06:19 PM Receipt #14029 RECEIVED FOR RECORD CHIPPEWA COUNTY - STATE OF NICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 11 PAGE 21

Register of Deeds Stamp & File Number

4. Lot No.

, Recorded Plat

5. Private Claims

I, Keith R. Waters, in a field survey on November 12, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration;

## G-2 1/2 Corner Common to Sections 3 & 4, T44N, R2W

1845 - Original corner established by James Mullett. Witnesses: Spruce 8, N75°E 34 links - Spruce 4, S72°W 13 links.

6 10 12

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Chippewa County Remonumentation Program. Found a 1/2" iron in the centerline of north-south road, on the extension of a fence line to the west. Found iron is on line between what appear to be offset irons 50.25 feet east and 50.25 feet west. Corner G-1 to the north, 2641.3 feet from section corner G-3 to the south, and is 6.4 feet east of a straight line between according corners. Accorded corner as found. between what appear to be offset irons 50.25 feet east and 50.25 feet west. Corner is 2661.7 feet from closing section

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

Found a ½" iron at the corner location, which falls 0.5'± east of the centerline of Hantz Road on the extension of an old fence line to the west, 14'± south of a newer fence line to the east. Witnesses:

Nail and plastic witness tag #33142 in side of Fence Post, N49°W 62.94' Nail and plastic witness tag #22428 in side of Fence Post, \$68°W 54.86' Nail and plastic witness tag #22428 in side of Fence Post, S48°E 70.20' Nail and plastic witness tag #22428 in side of Corner Fence Post, N78°E 55.25'

STATE OF MICHIGAN WATERS **PROFESSIONAL** 1 SURVEYOR Ma. 33142 PROFESSIONA

Keith R. Water

Date 12-30-98

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

BOOK 11 PAGE 21