

SURVEY &
REMONUMENTATION

APR 07 1998

Chippewa County Remonumentation Corner
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

SECTION

Chippewa

Located In:

Corner Code #

1. Public Land Survey

T 45N R 1E

F-3

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

\$7.00 LAND CORNER

\$2.00 MSSR

14 Jan 1998 3:35:55 PM Receipt #5566

RECEIVED FOR RECORD

CHIPPEWA COUNTY - STATE OF MICHIGAN
SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 10 PAGE 123

Register of Deeds Stamp & File Number

I, Larry R. Rogers, in a field survey on October 22, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

(F-3) 1/4 Corner Common to Sections 4 and 9, T.45 N., R.1 E.

Original corner post was placed in September, 1845 by James H. Mullett. 1919 County Surveyor notes call for post at 1/4 corner. In 1996, Ronald Bischer, P.S. 22428, found and used a 2 1/2" iron pipe approximately 6 feet West of a split between the Section corners to East and West and 1.75' North of a straight line between said Section corners.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F-3) 1/4 Corner Common to Sections 4 and 9, T.45 N., R.1 E.

This corner is being re-established as part of the Chippewa County Remonumentation Program.

Found 2 1/2" iron pipe used in Bischer survey, on North margin of beaver flooding. Accepted corner position as found and established new witnesses.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F-3) 1/4 Corner Common to Sections 4 and 9, T.45 N., R.1 E.

Corner is a 2 1/2" iron pipe on North margin of beaver flooding.

Witnesses:	12" White Birch	N69°W	19.82'
	10" White Birch	N30°W	33.18'
	8" Basswood	N71°E	27.60'
	4" Balsam Fir	S11°E	5.27'

Signed by

Date 19 DEC 1997

Surveyor's Michigan License No. 29251

NOTE: All bearings are compass bearings. All distances are to a nail in side of witness objects unless noted.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1995

BOOK 10 PAGE 123