## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Chippewa Co.

3 Corners.

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. 45 N. R. 1 E.	J-11, I-10, J-9	
2. PROPERTY CONTROLL- ING IN SECTION———	. ,T N. E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION	,T N E.		
4. LOT NO, REC			
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
I, David B. Babbitt			
A. Description of original monument and accessories and for subsequent restoration: J-11 South 1/4 Corner of Section 26. OBT'S: A 12" Fir for quarter post.			
I-10 West 1/4 Corner of Section 26. OBT'S: A Maple 10" in diameter.			
J <b>-9 N</b> orth 1/4 Corner of Section 26. OBT'S: Hemlock 10, S22 <sup>0</sup> E, 30 lks. and Fir 8, N41 <sup>0</sup> W, 12 lks.			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  J-11 Found old post point in center of abandoned E-W road grade and in line with old fence  North. I presume this post point to be the post set by the County Surveyor in his  1907 survey for a "Highway" on the South line of Section 26.			
I-10 Set M.P.O.L. between the N.W and S.W. Section Corners of Section 26.			
J-9 Set on line between the N.E. and N.W. Section Corners of Section 26 and in line with a very old fence remains South.			
-10 1" pipe W/plastic Tag in Power Pole, S85 <sup>0</sup> E, 60.5' & Tag	RLS Cap buried in Cen S89 <sup>0</sup> W, 47.1' & Tag i in Telephone Pole, N RLS Cap buried in Roa	iter Line of North - S in Fence Post, N43 <sup>0</sup> W, I37 <sup>0</sup> E, 89.6'. id. Bearings: 7" R.	e position of the corner: Tamarack, S19°E, 28.7' & South Road. Bearings: 58.2' & Tag in Fence Post, Maple, S20°E, 12.5' & W. Birch, N68°W, 72.25'.
SIGNED BY David B. Bab	B. Baffitt	DATE_ 7-17	2-84

21558

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO...