LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Chippewa Co.

2 Corners

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. 45 N., R. 1 K.	<u>I-11, I-12</u>	
2. PROPERTY CONTROLL- ING IN SECTION—	,T N. E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION =	,T N. E. W.		
4. LOT NO , R	ECORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER

- A. Description of original monument and accessories and/or subsequent restoration:
- I-11 S.W. Section Corner of Section 26. Wood Post. OBT'S: Tamarack 8, N16^OW, 21 lks. & Tamarack 10, S35^OE, 12 lks.
- I-12 West 1/4 Corner of Section 35. OBT'S: A Birch 10" in diameter.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- I-11 Set M.P.O.L. between the N.W. Section Corner of Section 26 and the S.W. Section Corner of Section 35 as described in the County Surveyors record of 1907. Falls in line with abandoned road grade East, and in center line of blacktop road North and South. Record states that the purpose of his survey was for a highway on the South line of Sec. 26.
- I-12 Set M.P.O.L. between the N.W. and S.W. Section Corners of Section 35.
 - C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- I-11 1" pipe W/plastic RLS Cap buried imcenter line of North and South Road. Bearings: Tag in Fence Corner, S78^oW, 51.35' & Tag in Power Pole, N74^oW, 47.6' & Tag in Fence Corner, S61^oE, 59.0' & Tag in Fence Post, S40^oE, 73.3'.
- I-12 1" pipe W/plastic RLS Cap buried 2.3' West of center line of North South Road. Bearings: Tag in Fence Post, N57°W, 55.45' & 8" Tamarack, S73°E, 64.8' & 6" Twin Cedar, S51°E, 70.6' & 10" Tamarack, S31°E, 88.7'.

SIGNED BY David B. Ballitt	DATE 9-17-84
David B. Babbitt	<u> </u>
SURVEYOR'S MICHIGAN REGISTRATION NO. 21558	(8EAL)
	e de la companya del companya de la companya de la companya del companya de la co