

MAR 06 1994

Chippewa County Remonumentation Corner

RECEIVED FOR RECORD  
CHIPPewa COUNTY  
STATE OF MICHIGAN

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

93 DEC 29 AM 10:26

For corners in

Chippewa  
(County)

Located In:

Corner Code #

1. Public Land Survey

T 46N R 1E

I-6

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

J. Roger Malott  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Larry R. Rogers, in a field survey on November 16, 19 93

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I-6) 1/4 Corner Common to Sections 14 and 15, T46N-R1E

This corner position was restored in 1984, on line between the Northeast and Southeast corners of Section 15 and on the extension of a fence line to the West. Corner was recorded in Liber 7, Page 14 of the Chippewa County Corner Records as a 1/2" iron with the following witnesses:

Fence Post	N40°W	71.41'	Corner Fence Post	N89°W	50.60'
Power Pole	S83°E	68.96'	Fence Post	S49°W	64.25'
Fence to East	South	7.00'			

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:


(I-6) This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

This corner was removed by the Chippewa County Road Commission during reconstruction of Riverside Drive and replaced with a monument box. Found 1/2" iron in monument box 0.8' East of centerline of Riverside Drive, on the extension of a fence line to the West and 7' North of a fence line to the East. Iron checks with four existing witnesses from 1984 record. Accepted corner position as found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I-6) Corner is a 1/2" iron with L.S. cap # 29251 in monument box.

Witnesses: Fence Post	N40°W	71.30'
Corner Fence Post	N89°W	50.75'
Fence Post	S49°W	64.30'
Utility Pole	S83°E	68.96'
Fence to East	South	7.00'



Signed by

Date 30 Nov 1993

Surveyor's Michigan License No. 29251

NOTE: Bearings are compass bearings corrected for declination.  
Distances are to a nail in side of witness objects unless noted.