

1999

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
Chippewa County Remonumentation Corner

SECTION

For corners in

<u>Chippewa</u>	Located In:	Corner Code #
1. Public Land Survey	T <u>46N</u> R <u>2E</u>	<u>D-3</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	
	S <u> </u> T <u> </u> R <u> </u>	
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	
	S <u> </u> T <u> </u> R <u> </u>	

\$7.00 LAND CORNER
\$2.00 MSSR
21 JAN 1999 10:25:59 AM Receipt #13123
RECEIVED FOR RECORD
CHIPPewa COUNTY - STATE OF MICHIGAN
SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK **10** PAGE **350**
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Larry R. Rogers in a field survey on October 15, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3				●									
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:
(D-3) 1/4 Corner Common to Section 5 and 8, Township 46 North, Range 2 East.
The original corner was placed in 1845 by James H. Mullett. County Surveyor records make no specific reference to corner. In 1975, a B.L.M. dependent resurvey found no corner and re-established the 1/4 corner at the intersection of an East - West dirt road and a North - South paved road. In 1981, William L. Karr, P.S. 27450 recovered a spike with an "X" chiseled on the head as placed in the road intersection by the B.L.M. and filed a L.C.R.C. in Liber 5, Page 075 of the Chippewa County Corner Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
(D-3) 1/4 Corner Common to Section 5 and 8, Township 46 North, Range 2 East.
Found spike with "X" on top under 3" of new asphalt 2 feet West of centerline of Homestead Road (North - South) and on centerline of 7 Mile Road (East - West). Recovered B.L.M. brass capped witness pipe to Northwest. Distances to Southwest and Southeast corners of Section 5 are both within 0.30 feet of B.L.M. distances. Accepted corner position as found and established new witnesses.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
(D-3) 1/4 Corner Common to Section 5 and 8, Township 46 North, Range 2 East.
Corner is a 12" spike with and "X" chiseled on top, 3" below grade and 2 feet West of the centerline of Homestead Road (North - South) and on an approximate centerline of 7 Mile Road to East and West.

Witnesses:
10" Spruce N55°E 50.17 feet
Southeast corner of phone box N38°W 53.69 feet
11" Spruce S52°W 74.63 feet
Utility Pole (SUI/135) S51°E 46.33 feet
B.L.M. Brass Capped Witness Pipe N46°W 50.40 feet



Signed by [Signature] Date 30 DEC 1998
License No. 29251

NOTE: All bearings are compass bearings corrected for declination (6°W). All distances are to a nail and tag in the side of witness object unless otherwise noted.