

MAR LS 1999

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Chippewa County Remonumentation Corner

For comers in

SECTION

Chippewa County	Located In:	Corner Code #	\$7.00 LAND CURNER \$2.00 MSSR
1. Public Land Survey	T <u>46N</u> R <u>2E</u> T R T R	G-4/5 ———	21 JAN 1999 10:06:56 AM Receipt #13123 RECEIVED FOR RECORD CHIPPENA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS
2. Property Controlling in Section3. Miscellaneous Property in Sec.	S T R S T R S T R R R R R R R R R R R R	#3	BOOK 10 PAGE 325 Register of Deeds Stamp & File Number
4. Lot No, Reco 5. Private Claims	rded Plat		1 A B C D E F G H J K L M 2 6 + 5 - 4 + 3 - 2 + 1 - 3
P.A. 74, Michigan P.A. of 1970, the c	n December 18, 1998, do hereby state orner points mentioned in lines 1 and 2	above were in conformance	5

States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: (G-4/5) Meander Corner between Sections 9 and 10, Township 46 North, Range 2 East.

The original corner was placed in 1845 by James H. Mullett. County Surveyor records make no specific reference to Meander Corner. in 1996, Ronald Bischer, P.S. 22428 placed the South 1/16th corner between Sections 9 and 10, and also set an iron pin 781.99 feet farther to the North.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (G-4/5) Meander Corner between Sections 9 and 10, Township 46 North, Range 2 East.

QVUMENT. This corner is being perpetuated as part of the Chippewa County Remonumentation Program. Found no evidence of the original corner position. Recovered Southeast corner of Section 9, South 1/16th Corner between Sections 9 and 10 and Bischer iron 781.99 feet North of 1/16th corner. Re-established Meander Corner on line between Sections 9 and 10 as surveyed by Bischer and at record G.L.O. distance North of Southeast Corner of Section 9 (1452 feet). The re-established position is 650 feet South of Northerly most corner placed by Bischer and on a North/South brush line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (G-4/5) Meander Corner between Sections 9 and 10, Township 46 North, Range 2 East. Corner is a 3/4" x 48" rerod with stamped aluminum cap set 1 foot above grade in very swampy area.

Witnesses:

Signed by

Bischer 1/2" iron pin (1/16th)	South	143.76 feet
Bischer 1/2" iron pin	North	650.0 feet
Capped Witness Pipe	N67'W	27.31 feet
Capped Witness Pipe	S54*W	29.84 feet
Capped Witness Pipe	S60*E	11.77 feet
Capped Witness Pipe	N32'E	13.23 feet
Steel Fence Post	North	2.0 feet

OF MICHIG LARRY R. **ROGERS** and Surveyor NO. 29251

Surveyor's Michigan License No. 29251

NOTE: All bearings are compass bearings corrected for declination (6°W). All distances are to a nail and tag in the side of witness object unless otherwise noted.

Date _ 28 Dec /998

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995