FEB 2 3 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Chippewa County Remonumentation Corner

For corners in

Located in: Corner Code # Chippewa County **T47N R2E** Public Land Survey T R R T T R 2. Property Controlling S T R R in Section S T 3. Miscellaneous S T R S Property in Sec.

\$7.00 LAND CORNER

\$2.00 MSSR

9 FEB 2001 10:29:00 AM Receipt #1201 RECEIVED FOR RECORD CHIPPEWA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS

PAGE 219 BOOK 11

Register of Deeds Stamp & File Number

Lot No.

, Recorded Plat

Private Claims

I, Larry R. Rogers, P.S., in a field survey on December 18, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

3. 12 13

A. Description of original monument and accessories and/or subsequent restoration: (C-3) Section corner common to Sections 6, 5, 7 and 8, Township 47 North, Range 2 East.

John Mullett set original section corner post in 1845 and established a 10" spruce N52E 14 lks and an 8 ceda Saw 23 lks as witnesses. County Surveyor records of unknown date indicate that the corner is a 4" cedar post and a 36" bolt with the following witnesses; 6" Birch N70E 58 feet, 6" Birch S56E 57 feet, and a 10" Birch S78°W 37 feet. In 1996 W.L. Karr, P.S. 27450 found a 1/2" iron in the centerline of Brasser Road, accepted corner as found, and used it in a survey. No corner ties were established at that time.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (C-3) Section corner common to Sections 6, 5, 7 and 8, Township 47 North, Range 2 East. This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found 1/2" iron in centerline of Brasser Road matching distances on W.L. Karr's certificate of survey. Excavated around 1/2" iron and found that iron had been placed in old wood post approximately 1 foot below grade. Accepted corner position as found and replaced 1/2" iron with 3/4" iron and established new witnesses. Testimony from two local land owners indicated that the corner is in the appropriate position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (C-3) Section corner common to Sections 6, 5, 7 and 8, Township 47 North, Range 2 East. Corner is a 3/4" iron with plastic Chippewa County remonumentation cap driven into an old rotted wood post and left 6" below grade in centerline of Brasser Road (gravel), corner falls approximately 32 feet North of the centerline of Leask Road (gravel) to the East.

Witnesses:

109.00 feet (In yard no blaze) 16" Yellow Birch N68°W 30.85 feet N76°E Utility pole SU1/25B/17 Anchor Pole S12°E 81.89 feet 71.33 feet S42°W 6" Yellow Birch

s are to a mill and tag in the side of the witness object unless otherwise Bearings are magnetic compass bearings. All distant noted.

> LARRY 8. **ROGERS** and Surveyor

> > LAND

Signed by Larry R. Rogers, P.S Surveyor's Michigan License No. 29251

NO. 29251

REVISED OCT., 1995

800K 11