

Chippewa County Remonumentation Corner

RECEIVED FOR RECORD
CHIPPEWA COUNTY
STATE OF MICHIGAN

LAND CORNER RECORDATION CERTIFICATE

93 DEC 29 AM 10: 26

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Chippewa

(County)

Located In:

Corner Code ##

J. Roger Malott
REGISTER OF DEEDS

1. Public Land Survey

T 46N R 2W B-1/C-1 \ Same
T 47N R 2W #1 B-13/C-13/CORNER2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

SURVEY &
REMONUMENTATION

JUL 22 1999

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____ SECTION _____

5. Private Claims _____

I, William L. Karr, in a field survey on December 9, 19 93

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(B-1/C-1) Witness Corner to Meander Corner Section 6 (T46N, R2W) and
Section 31 (T47N, R2W)

1840 William Burt, D.S.

Set Post

Cedar 12 N48°W 25 links

BLM conducted a dependent re-survey of the area in June of 1975. Meander corner was not set in this survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(B-1/C-1) This corner is being re-established as part of the Chippewa County Remonumentation Program.

Found no evidence of original corner. Position now falls in Waiska Bay. BLM in 1975 did not find corner but established Township line and computed pro-rated position for Meander corner but did not monument. Corner was computed on a straight line extension from the Township corner East through 1/4 corner 6/31. We recovered the Township corner and 1/4 corner 6/31 and extended a line through these corners to the currently existing high water line to establish the Witness Corner to the Meander Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B-1/C-1) Corner is a 3/4" x 24" iron with 3" diameter stamped aluminum cap, P.S. #27450. Corner falls at Toe of filled area. Actual edge of water is approximately 190' to the East (Shoreline is grassy and not well defined). Corner falls 54' North of North range of house to West.

Witnesses: 6" Maple N36°W 56.43'
9" Spruce N03°E 11.92'
13" Poplar S13°E 60.69'
6" Ash S59°W 32.31'Signed by William L. KarrDate 12/14/93Surveyor's Michigan License No. 27450NOTE: Bearings are compass bearings corrected for declination.
Distances are to a nail in side of witness objects unless noted.FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

L. 8 pg 128 Other code: 1