

SECTION

LAND CORNER RECORDATION CERTIFICATE CLINTON COUNTY REMONUMENTATION WEST 1/4 CORNER, SECTION 19, T5N-R2W DEWITT TOWNSHIP

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER OOL PAGE 344

RECOMMED

	Limit today	
For corners in Clinton (County)	Located in:	Corner Code #
Public Land Survey	T_5N_R_2W_ TR TR	A-8
Property Controlling In Section Miscellaneous Property in Sec. Lot No. Private Claims	S T R S T R S T R S T R S Recorded Plat	

DEC 21 12 49 PM '99 REGISTER OF DEEDS CLINTON COUNTY, MICH.

Register of Deeds Stamp & File Number

C

Q

10

11 12

I, Mark L. VanRaemdonck, in a field survey on, September 8, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Department of the Interior, Eureau of Land Management of by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be

- A. Description of original monument and accessories and/or subsequent restoration: recorded on this certificate.
 - 1. Original: Not a G.L.O. comer. Found no record of evidence of ancient corner.

2. Nelson C. Jones, L.C.R.C., signed by Arden S. Pierson, as crew chief.

2. Nelson C. Jones, L.C.R.C., signed by Arden S. Pierson, as crew chief.

12. Recorded Liber 1, page 129, January 31, 1972.

Recorded Liber 1, page 129, January 31, 1972.

Monument: Dug, but did not find evidence of corner being established. Fence to East appears to Monument: Dug, but did not find evidence of corner being established corner from the Northwest being error. Established corner on Township Line at proportionate closing distance from the Northwest and Southwest corner of said Section from the standard 1/4 corner for the East 1/4 corner of Section 24, T5N-R3W. This also places the West 1/4 corner of Section 19 midway between the Northwest and Southwest corner of said Section. Set 1/2" Copperweld in monument box.

Accessories: S45°E 37 83' Wood corner fence post Accessories: \$45°E 37.83' Wood corner fence post

S75°W 64.77' Power pole S65°E 29.09 Telephone pole

3. Ron Heisel, Certified Survey, recorded Liber 1, page 205, survey date September 11, 1972.

Monument: 1/2" rod in monument box.

Accessories: Same as No. 2 above.

4. Richard W. Steadman, Certified Survey, recorded Liber 1, page 272, March 22, 1973. Monument: 1/2" rod in monument box. Accessories: Same as No. 2 above.

5. M.D.O.T. plans for project: I-69-3 (33) 83, July 7, 1981. Monument and accessories same as No. 2 above.

6. Kay Don Fluke, L.C.R.C., recorded Liber 2, page 518, August 10, 1984. Kay Don Fluke, L.C.R.C., recorded Liber 2, page 516, August 10, 1984.
 Monument: Found 1/2" Copperweld in monument box.
 Accessories: S90°W 112.52' Power pole
 Accessories: S90°W 68.37' Steel sign post N25°W 68.37' Steel sign post N00°21'53"E (no distance) 3/4" pipe with M.D.O.T. cap in mon. box S10°E 121 11' Steel sign post

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found 1/2" Copperweld in monument box as referenced in No. 2 above and No. 6 above. Found no

Found 1/2" Copperweld in monument box as reterenced in No. 2 above and No. 5 above. Found no conflicting evidence and accepted this location as the careful and faithful establishment of the original

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Set a standard Clinton County Remonumentation monument, being a 2 ½" diameter steel tube, 30" long with a standard brass cap, stamped "P.S. 24622", and a breakaway magnetic base at the corner location described in Section B above. The monument is witnessed by the following accessories:

N20°W 52.81 Set R&C in asphait road shoulder NZU VV 52.01 SEL N&T E. face uitt. Pole \$75W 101.81' Sel N&T E. face uitt. Pole NO0°10'50"E 9.92' Remon Monument at M-8

S25°W 58.30' Set R&C in asphalt road shoulder 520 W 56.50 Set Rac III aspirate road shoulder \$70°E 31.82' W. edge W. leg sign \$00°10′50″W 2634.90' Remon Monument at M-9

MARK L.

* VANRAEMDONCK *

PROFESSIONAL ME
SURVEYOR

No.
24622

CLINTON COUNTY PEER GROUP DATED 3/8/99 APPROVED BY

Date OCT. 20, 1999 Bearings to M-8 and M-9 are based on solar observation

LLVER Signed by Surveyor's Michigan License No. 24622

FORMAPPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS

JAN 18, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983