

LAND CORNER RECORDATION CERTIFICATE SECTION Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Corner Code # Located in: Crawford (County) J 26NR 2W 27N R 2W T27/ R 3 W T36/ R 3/L R in Section S 2 п Property in Sec. S

1. Public Land Survey 2. Property Controlling 3. Miscellaneous , Recorded Plat 4. Lot No. 5. Private Claims

I, Marvin E. Myers, in a field survey on 27 MAY, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

G.L.O. 15 June 1852 Darwin A. Pettibone D.S. Mon: Post

Wit: 24" Pine \$71°W 1.00 links 18" Yellow Pine N80°E 1.29' links' 12" White Pine N18°W 0.94 links

Eugene Ostling R.L.S.#12026

Mon: 3/4" square Iron

Wit: none provided

Unrecorded survey, 4 Sept 1971

1955 George D. Henning R.L.S. Unrecorded Survey Sec.6 T26N R2W Restored from stumps of original U.S. witnesses

Mon: 3/4" square bar in blacktop 9' N. of centerline

Wit: 4" Jack Pine N58°W 58.1 8" Jack Pine N41°E 37.00' 7" Jack Pine S31°W 62.0'

Norman F. Parker R.L.S.#16939 Liber 148 Page 07, 26 Sept 1975 Mon: no description provided Wit: none provided


STATE OF MICHIGAN CRAWFORD COUNTY RECORDED

> SANDRA MOORE REGISTER OF DEEDS

19 DEC 97 2:36 P.M.

Register of Deeds Stamp & File Number

PAGE



Robert T. Ostling R.L.S.#5133 Liber 1 Page 59, 14 August 1959 Plat of Ausable Trails Mon: 3/4" iron in pavement Wit: none provided

Norman F. Parker R.L.S.#12026 Unrecorded survey 29 Dec 1986

Mon: no description provided Wit: none provided

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found Rall Road spike flush with the asphalt surface 8.5' north of centerline. Verified position by measurement to corners East and West. Accepted position as a perpetuation of the original government Corner, replaced railroad spike in exact location with standard County Monument in pavement monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Mon - Standard Crawford County monument in Pavement Monument box.

Wit: Spike in Southeast side Utility Pole S53°W 60.60 Set spike in West side 13" Red Pine S36°W 76.90" Set spike in East side 8" White Pine \$38°E 87.60' Set spike in 8' Jack Pine N20°W 43.63'

CRAWFORD COUNTY PEER GROUP APPROVAL

DATE 007 /6, 1997 Marry E. Myen

> Marvin E. Myers, P.S. **County Surveyor**

RIFE MARVIN BAYEDS

Surveyor's Michigan License No. 31600

Date 84 (5,1997

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 16 REVISED MAY 14,16 REVISED JAN., 19 REVISED CCT., 15