

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Cheboygan  
(County)

Located In

Corner Code #

1. Public Land Survey	T	36N	R	1W	E4
	T	36N	R	1W	E5
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on September 16, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

E4 - 1/4 Corner comm. to sec.'s 8&9, T36N,R1W

E5 - Section Corner comm. to sec.'s 8,9,16,17, T36N, R1W

1855 - GLO - Harvey Mellen  
Beech 12" N34 1/2°E 28 Links  
Beech 8" N25 1/2°W 30 Links

1855 - GLO - Harvey Mellen  
Elm 10" S60°W 1.30 Chains  
Elm 6" S35°W 85 Links

1903 - County Surveyor Record,p.196 - David Bowen,  
Cedar Post 3" square set in road.  
1971 - Survey Notes - Doyle Civil Engineers - Orlando Doyle,  
P.S.,P.E.#7319 - Indicates corner.  
1979 - Survey Map - MDOC - Kenneth J. Ostling, P.S.#10068 - Shows  
found 1/2" square iron bar and distances N-S & W.  
1999 - Cert. of Survey - James H. Granger, P.S.#16041 -  
Fd. 5/8" rod w/ 1 1/2" flared head in mon. box.  
2004 - L.C.R.C. - L.4,p38 - James H. Granger, P.S.#16041 - same info  
as above. P.Pole S56°E 71.03' set N&T; 1/2" rebar w/cap#16041 N80°W  
33.08'; 1/2" rebar w/cap#16041 S62°W 39.94'; 1/2" rebar w/cap#16041  
N05°W 155.77'

1903 - County Surveyor Record,p.196 - David Bowen,P.S.  
Cedar Post 3" square set in road.  
1971 - Survey Notes - Doyle Civil Engineers - Orlando Doyle,  
P.S.,P.E.#7319 - Indicates corner.  
1979 - Survey Map - MDOC - Kenneth J. Ostling, P.S.#10068 - Shows  
R.R. spike in mon. box w/distances North and West.  
1999 - Cert. of Survey - James H. Granger, P.S.#16041 - Fd. 5/8" rod w/  
1 1/2" flared head in mon. box.  
2004 - L.C.R.C. - L.4,p38 - James H. Granger, P.S.#16041 - same info  
as above. Guard Rail Post S22°E 34.72' set N&T; Guard Rail Post  
S52°E 33.22' set N&T; Guard Rail Post S45°W 37.79' set N&T; 1/2"  
rebar w/cap#16041 N80°W 33.09'  
2004 - Cert. of Survey. - L.964,p480 - James H. Granger, P.S.#16041 -  
same info as above.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

E4 - 1/4 Corner comm. to sec.'s 8&9, T36N,R1W

E5 - Section Corner comm. to sec.'s 8,9,16,17, T36N, R1W

Found 5/8" rod w/alum. cap in mon. box 1' West of N-S C/L blacktop road.  
Fence line running West from corner. Accepted found rod as the best  
available evidence for the position of the original corner. Found no other  
evidence to dispute the location for the corner.

Found 5/8" rod w/alum. cap in mon. box 3' East of N-S C/L blacktop road.  
Corner is in line with C/L gravel road to East. Accepted found rod as the  
best available evidence for the position of the original corner. Found no  
other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E4 - 1/4 Corner comm. to sec.'s 8&9, T36N,R1W

E5 - Section Corner comm. to sec.'s 8,9,16,17, T36N, R1W

5/8" rod with stamped 1 1/2" alum. cap in mon. box.  
Witnesses:  
N65°W 69.49' to set N&T on N side P.Pole  
S57°E 71.44' to set N&T on N side P.Pole  
S63°W 39.85' to 1/2" CIR#16041  
N79°W 33.01' to 1/2" CIR#16041

5/8" rod with stamped 1 1/2" alum. cap in mon. box.  
Witnesses:  
S41°W 37.98' to fd. N&T on NW side Guard Rail Post  
N16°W 128.46' to set N&T on E side 8" Ash  
S62°E 113.08' to set N&T on S side Guy Pole  
S42°E 29.95' to set N&T on SW side Guard Rail Post

\* Previous recorded witness.

\* Previous recorded witness.

Carl T Kiiskila

2-25-10

Surveyor's Michigan License No.: 33981

