

CHEBOYGAN COUNTY REMONUMENTATION CORNER

**LAND CORNER RECORDATION CERTIFICATE
Requirement of Act 74, Mich. P.A. 1970**

For corners in

<u>CHEBOYGAN</u> (County)	Located in:	Corner Code #
	<u>38N 2W</u>	<u>F-13</u>
1. Public Land Survey	<u>T 37NR 2W</u>	<u>F-1</u>
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____

RECEIVED FOR RECORD 12-18-97
at 11:29 O'Clock A M
James H. Granger
CLERK/REGISTER
CHEBOYGAN COUNTY, MICHIGAN
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, JAMES H. GRANGER, in a field survey on JULY 15, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F-1 1840 Original Survey Set wood post 10" Cedar N38°W 23 lks
John Mullett 8" Cedar N56°E 12 lks
1955 Survey 3/4" pipe
Orlando Doyle #7319

**SURVEY &
REMONUMENTATION**
FEB 26 1998
SECTION

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-1 Found 3/4" pipe at corner position. Replaced with 5/8" rebar and remonumentation cap.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-1 5/8" rebar and Remonumentation Cap
4" Cedar S 4°E 18.86' Set tag #16041
14" Poplar S37°W 24.25' Set tag #16041
4" Poplar N79°W 38.50' Set tag #16041
4" Maple N37°E 17.04' Set tag #16041

Signed by James H. Granger Date Nov 17, 1997 Surveyor's Michigan License No. 16041

