## SURVEY & REMONUMENTATION

MAR 2 1 1997 COMMISSION () DELTA CO Approved By Delta County Land Survey Remonumentation Peer Group Under Act 345 Of

COUNTY CODE NO.	P.A. Of 1990 On /2/22 , 1994
LAND CORNER RECORDATION CERTIF	mules hureling
LAND CORNER RECORDATION CERTIF	ICATE active Chairman

For corners	in		Filing Requi	rement of Act 74, M	ich. P.A. 1970		
	DELTA				1		
	(County)	L	ocated In:	Corner Code ##	1	0	21997
					n:	corded	<del></del>
1. Public L	and Survey		T 38 N B23 W	- <u>MC-A\B-11</u> -((7)	at.	3:00 Greek_	PM
			T 38 N = P23 N	MC B/C-11 (8)	<del>)</del>   L8	ter <i>B</i> Pace	196
	•		TR(	other #	_	Wallace C.	ZZ.
2. Property	. Controlling		T R		-··· <u>C</u> e	312 County, 1 Exc pt of Glading	
in Section			T R T R		— [		
3. Miscella			T R		_   _		
Property			T R		— Heg	ister of Deeds Stam	ip & File Number
-							
		Recorded Pla	at			ABCDEF	· G. H + J K L
5. Private C	Claims	DD 000 II 000					
. ML MC	A\B-11 (MEANU) D\C_11 (MEANU)	ER COR W. SIDI	OF LAKE- S. LINE	S.30)		2 6 5 4	3 - 2 - 1 -
FIC	D/C-II (MERNO)	ER COR E. SIDE	OF LAKE- S. LINE	8.30)		3	
M.P. D	AVIS	in a fintal a	MARCH/M	AY	. 06	4 7 4 9	-10-11-12-
';		ouirements of	rurvey on <u>timicin</u> in P.A. 74. Michigan P.A	of 1970, the corner points	smentioned	5	
in lines 1 and	l 2 above were	in conformanc	e with regulations a	nd rules therefore as req	uired in the	6 18 17 16	15-14-13-
Current manua	al of survey inst	ructions of the	United States Depa	rtment of the Interior, Bur	eau of Land	7	<del>-                                     </del>
above were in	conformance v	racount or Law	the Michigan Board	er points mentioned in line of Land Surveyors or by a	es 3, 4 and 5 Decree of a	8 19 20 21	22 23 24
Court of Law	r, established,	re-established	i, monumented, re	monumented, recovered	, found as	9	
expressed be						10 30 29 28	272525
			n the same town a	nd range, may be reco	orded	11	<del>-                                     </del>
on t	his certificate	<b>)</b> .				12 31 32 33	34-35-36-
A Descript	ion of original	monument a	nd accessories ar	id/or subsequent resto	ration:	13	
A\B-11 [MC	S.LINE S30] W	OOD POST - A.	MERRYWEATHER, D.S.	- 1847 (TAMARACK 10°-N	60°W-50 LINKS)		
J.E.	GINGRASS-1933-	WOOD POST FOU	ND IN PLACE-NO NEW	WIT'S NOTED OR DESCRI	PTION OF MONUMEN	NT GIVEN.	
B/C-11 IMC	S.LINE COR S3	0] WOOD POST	- A.MERRYWEATHER, I	.s 1847 (CEDAR 07"-	N44°E-42 LINKS)		
r kom Propo	PRIVATE RECUR DRTIONATE MEAS	DS OF M.S.MCN UREMENT BRYWR	ABB-SURVEY BY J.E. N MC ON WEST SIDE	GINGRASS, 1933 - INDIC OF LAKE & SEC CORNER TO	ATES CORNER POST	ITION ESTABLISHED BY	SINGLE
		OKEHOKI EGIRE	W TO AM WHOT DIAT	OL BUND & ORC CONNEW IN	O IRE EMOI.		
						-	
B. Descript	ion of corner	evidence four	nd and/or method	applied in restoring or	reestablishing of	corner:	
a/bail fur	-UC.6 ANLU .6 הסדת שהגשמושקו	WEST SIDE OF	LAKEJ EXTENDED LIN	E WEST FROM NE COR S.30	O THRU MC FOUND	IN PLACE ON EAST SHO	RE OF LAKE & AT THE
POLE	18' TO 9' LON	anca wasi ur i G wiph the to	NG UN ING KAST SHU P 18 m/t. SHAVED C	RE I FOUND (DOWN AND IN N TWO SIDES). NO OTHER	N THE LAKE MUCK)	WHAT IS BELIEVED TO	BE GINGRASS'S SITE
CORNE	R POSITION ON	LINE WITH TE	NE COR OF S.30 &	THE MEANDER CORNER, AS	FOUND ON THE R	OANDA MUNUMBNI FOUND AST SHORE OF THE LAK	. ISIADDIONEU A NEW R IND IT I
PROPO	RTIONATE DIST	ANCE WEST OF	PHE EAST MC. ACCEP	TED THIS POSITION AS BE	EING THE BEST AV	'AILABLE EVIDENCE AS	TO THE LOCATION OF
THE P	OSITION OF TH	E ORIGINAL CO	RNER				
DIA II IVA	A						
B/C-II [MC	S. LINE S.30-	EAST SIDE OF I	JAKE) FOUND IN PLA	CE A SQ'D CEDAR POST SC	CRIBED "MC" NO O	THER EVIDENCE FOUND.	ACCEPTED EXSITING
MONUM 4771	IBRI AS INE UN. TEN EYICTING !	MUNUMBND 36 DI R ROLARPIOHEN	IN 1933 BY J.E.GI	NGRASS AS DISTANCE EAST	TO SEC CORKER	CHECKS WELL WITH THE	RECORDS OF GINGRASS.
ncesi	TOD EXISTING	MORGHANI NO DI	ting a CAREFUL & F	AITHFUL REESTABLISHMENT	OF THE PUSITION	N OF THE ORIGINAL CO	RNER.
						<b>1</b> 6	OF MICH
						<b>y</b> /,	X France A
_						3/6	M. P.
				established to perpetua		position of the corp	TE DAVIS
A\B-11 SET	A BERNTSEN All	VB30 ALUMN MON	IUMENT W/A 31/4" C	AP STAMPED TO ID THE CO	RNER POSITION.	3 3	LAND SURVEYOR
CEDA S38		CEDAR 08" N47'W	CEDAR 06"	SURVEY MONUMENT SIGN P	POST	4 3	No.
12.		16.32'	NO8°W 28.28'	N71°W		3/2	16926
12.		10.32	40.20	1.20' (TO FACE)			Tea RIV
B\C-11 REPL	ACED WOOD POST	W/A BERNTSEN	A12NB30 ALUMN NO	NUMENT W/A 31/4" CAP ST	AMPED TO ID THE	ר אחדת פחק אומפטן מחודת פחק אומפטן	LAND SO
CEDAR	7 T CEDAR	₹6" CE	DAR 7" SUR	YEY MONUMENT SIGN POST		Souther Louision.	A DAMAGE
	W N26°		60°E	S19°E			
18.5	5' 9.72	! <i>'</i> 1	5.83'[	2.59' (TO FACE)			
NOTE: BEARII	NGS TO REFEREN	CE OBJECTS AR	E MAGNETIC - DISTA	NCES ARE TO A NAIL IN	THE CENTER OF TH	HE OBJECT UNLESS NOTE	D OTHERWISE
Ci-wa-di	/	Be have	7		mla, l	,	
Signed by		יון בארוארים וין		Date	14/20/9	76	
Surveyor's Mi	chigan Licens	se No	724				