MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 39 NR 18 W

		- LU B - L & B COUNT
DESCRIPTION	OF CORNE	R 1/4 comer between Sections 22 and 23
DESCRIPTION	OF CORNER	MONUMENT_l"_Pipe_with_4"_Brass_Cap
WITNESSES	TO CORNER	4" Cedar (1/4s NBT) N 8° W 11 Links
		4" Cedar (1/4s NBT) _ S 82° W _ 15 1/2 Links .
		·

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from probable B. T. a rotten Hemlock Stump bearing S 66° E 14 Links. Position fits swamp edges and a small lake to south. Found old blazes at corner.

Corner was placed and witnessed October 21, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 2/23/60 REGISTERED LAND SURVEYOR

Billy D. Buckler