

SURVEY & REMONUMENTATION

FEB 02 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Approved By Delta County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On December 30, 1998
Walter C. Flinn
Chairman

For corners in
DELTA
(County)

Located In:

Corner Code ##

1. Public Land Survey
T 40 N R 19 W
T 40 N R 19 W
T R
T R
2. Property Controlling
in Section S T R
S T R
3. Miscellaneous
Property in Sec. S T R
S T R

MC E-1/2 (25)
MC E-8/9 (13) ✓

Recorded Jan 4 1999
3:40 PM
9 112
Walter C. Flinn
Delta County, MI Reg. of Deeds

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____
E-1/2 [MC SEC 5/4] E-8/9 [MC SEC 20/21]

I, M.P. DAVIS, in a field survey on DECEMBER, 19 98, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-1/2 [MC SEC. 5/4] A.MERRYWEATHER, D.S. - 1848 - WOOD POST - (TAMARACK 06° S70°W 62 LINKS)
NO RECORD EVIDENCE OF SUBSEQUENT CORNER RECOVERY AND/OR RESTORATION

E-8/9 [MC SEC 20/21] A.MERRYWEATHER, D.S. - 1848 - WOOD POST (WILLOW 04°-N25°E-32 LINKS)
NO RECORD EVIDENCE OF SUBSEQUENT CORNER RECOVERY AND/OR RESTORATION

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-1/2 [MC SEC. 5/4] NO CORNER EVIDENCE FOUND. REESTABLISHED CORNER POSITION AT "GLO" BEARING AND DISTANCE SE OF THE MC, AS ESTABLISHED BY B.L.M. SURVEY CREW IN 1997, ON THE 4TH CORRECTION LINE NORTH AT ITS' INTERSECTION WITH THE WESTERLY SHORE OF MOSS LAKE. THIS POSITION FITS WELL WITH THE PRESENT SHORE LINE OF MOSS LAKE.

E-8/9 [MC SEC 20/21] NO CORNER EVIDENCE FOUND. REESTABLISHED CORNER POSITION BY IDENTIFYING M.S. McNABB'S SECTION LINE X-ING AS FOUND IN HIS 1933 ROAD ALIGNMENT SURVEY OF COUNTY ROAD 499 EXTENDING A LINE SOUTH FROM THE WEST 1/4 COR OF SEC 21 THRU McNABB'S X-ING POINT AND ESTABLISHING THE M.C. ON THIS LINE AND AT THE "GLO" DISTANCE (2451.9') SOUTH OF THE 1/4 CORNER. THIS AREA HAS BEEN ARTIFICIALLY FILLED AND THE MOUTH OF THE STURGEON RIVER HAS APPARENTLY BY REROUTED DURING THE DEVELOPEMENT OF THE SMALL VILLAGE OF NAHMA AS THE CORNER POSITION FALLS A CONSIDERABLE DISTANCE FROM THE RIVER & LAKE MICHIGAN.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-1/2 SET BERNTSEN AINB30 ALUM MONUMENT W/A 3 1/4" CAP STAMPED TO ID THE CORNER POSITION.
TAMARACK 09° TAMARACK 10° TAMARACK 11° TAMARACK 15° SURVEY MONUMENT SIGN POST
S80°E S18°E S85°W N40°W NORTH
05.12' 12.49' 17.20' 17.57' 1.84' (TO FACE)

E-8/9 SET BERNTSEN AINB30 ALUMN MON. W/A 3 1/4" CAP STAMPED TO ID THE CORNER POSITION.
OAK 10° OAK 09° SURVEY MONUMENT SIGN POST NOTE: OPEN & TAG ALDER LAND IN THE NE & NW QUADRANTS
S35°E S40°W SOUTH
14.25' 54.91 1.31' (TO FACE)

BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC-DISTANCES ARE TO A NAIL W/A DELTA COUNTY REFERENCE TAG, UNLESS OTHERWISE NOTED.

Signed by M.P. DAVIS Date 12/28/98
Surveyor's Michigan License No. 16926

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		3		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

