

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
DELTA
(County)

Located In:

Corner Code ##

MAY 13 1994

1. Public Land Survey

T 40 N R 24 W

I-3

T _____ R _____

T _____ R _____

T _____ R _____

2. Property Controlling
in Section

S _____ T _____ R _____

S _____ T _____ R _____

3. Miscellaneous

S _____ T _____ R _____

Property in Sec.

S _____ T _____ R _____

Recorded

9:00 AM In Lib 7 Page 406

Robert A. Shumling Reg. of Deeds

Delta County, Michigan

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I-3 [SW COR SEC 2] J-3 [S1/4 COR SEC 2]

I, M.P. DAVIS, in a field survey on MARCH, 19 94,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-3 [SW COR SEC 2] HARVEY MILLEN, D.S. - 1852 - WOOD POST (CEDAR 14"-S23°W-36 LINKS) (CEDAR 14"-N02°W-15 LINKS)
1915 - M.S. McNABB, ROAD ALIGNMENT SURVEY FOR CORNELL TWP. - ID COR POSITION FROM ORIGINAL CEDAR BT SW- RESET STAKE & BT STAKES NW &
SE 33'

J-3 [S1/4 COR SEC 2] HARVEY MILLEN, D.S. - 1852 - WOOD POST - (SUGAR 12"-N48°W-17 LINKS) (SUGAR 12"-S43°E-25 LINKS)
1915 - M.S. McNABB, ROAD ALIGNMENT SURVEY FOR CORNELL TWP. - ID CORNER POSITION BY STAKE IN PLACE - SET BT STAKES NE & SW 33'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-3 [SW COR SEC 2] NO EVIDENCE OF McNABB'S 1916 SURVEY MONUMENT FOUND - RESTORED CORNER POSITION
BY RETRACEMENT OF McNABB'S 1915-1916 ROAD ALIGNMENT SURVEY BETWEEN THE SW COR OF SEC 5 & THE
S1/4 COR OF SEC 2. ACCEPTED THIS POSITION AS BEING A CAREFUL & FAITHFUL PERPETUATION OF THE
OF THE ORIGINAL CORNER.

J-3 [S1/4 COR SEC 2] NO EVIDENCE OF McNABB'S 1916 SURVEY MONUMENT FOUND - RESTORED CORNER POSITION
BY RETRACEMENT OF McNABB'S 1914 SURVEY OF THE N-S 1/4 LINE OF SEC 2- FOUND McNABB'S N1/4 & C1/4
CORNERS & EXTENDED A LINE SOUTH FROM THE N1/4 COR THRU THE C1/4 COR & SET THE S1/4 COR ON THIS LINE
AT A PROPORTIONAL DISTANCE SOUTH OF THE C1/4 COR (BASED ON McNABB'S DISTANCES)
ACCEPTED THIS POSITION AS A CAREFUL & FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-3 SET, INSIDE A MONUMENT BOX, A 5/8" X 18" REBAR W/A 3-1/4" ALUMN CAP STAMPED TO ID THE CORNER POSITION.
POWER POLE SURVEY MONUMENT SIGN POST BALSAM 8" SPRUCE 13" CEDAR 7"
N54°W SOUTH S44°E S34°W N53°E
47.10' (TO FACE) 19.85' (TO FACE) 55.86' 39.38' 53.76'

J-3 SET, INSIDE A MONUMENT BOX, A 5/8" X 18" REBAR W/A 3-1/4" ALUMN CAP STAMPED TO ID THE CORNER POSITION.
MAPLE 14" SURVEY MONUMENT SIGN POST MAPLE 14" NW COR HOUSE POWER POLE
N05°E NORTH N33°W S44°W S50°E
52.78' 26.90' (TO FACE) 51.67' 123.30' 37.54'

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC & DISTANCES ARE TO A NAIL W/A REFERENCE TAG, UNLESS NOTED OTHERWISE

Signed by M.P. Davis Date 4/4/94

Surveyor's Michigan License No. 16926

