

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 40 N. R. 29 E. W.	I 8 & J 9
2. PROPERTY CONTROLLING IN SECTION	23 T. 40 N. R. 29 E. W.	10
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		REGISTER OF DEEDS STAMP AND FILING NUMBER

I, **Arthur O. Enger** do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970 the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on **see below** 19, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner I 8: Wood post	Not found.	No subsequent monuments found
Birch 12 N70E 20	" "	No subsequent accessories found.
Birch 6 N35W 30	" "	" "
Corner J 9: Wood post	Not found.	Found a 2" O.D. x 54" iron pipe.
Sugar 10 N45E 25	" "	No subsequent accessories found.
Birch 12 S10E 8	" "	No subsequent accessories found.
Corner 10: Not established in original survey nor subsequently, apparently.		

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner I 8: Re-established 7/5/72 on line between section corners 40.500 ch. S and 41.784 ch. N. Position on line determined by the falling with natural features called for in original field notes, rather than proportionately, to achieve conformity with conditions on the ground. Corner lies 1 ch. S of swamp edge, as per original notes.

Corner J 9: Replaced the found pipe on 7/10/72. Pipe is identical with one found at Corner I 11, this township, and may have been set by same party. Both pipes very old, and original evidence may have been present when set. This pipe is 40.107 ch. W of an original corner and checks with stream crossings to W.

Corner 10: Established 7/5/72 on line between sec. corner 20.250 ch. S and 1/4 corner

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Monuments for all three corners: 1" I.D. x 36" iron pipe with 4" aluminum cap. 20.250 ch. N.

Witnesses to Corner I 8:	Cherry 6 N58°E (mag.) 12.6 ft. "1/4S, NBT"
	Elm 6 S 6°E (mag.) 16.8 ft. "1/4S, NBT"
	Elm 4 S49°W (mag.) 21.6 ft. "1/4S, NBT"
Witnesses to Corner J 9:	Red Maple 5 S26°W (mag.) 17.6 ft. "1/4S, NBT"
	Elm 5 N45°W (mag.) 22.5 ft. "1/4S, NBT"
	Elm 5 S11°E (mag.) 7.3 ft. "1/4S, NBT"
Witnesses to Corner 10:	Sugar Maple 5 S62°W (mag.) 12.7 ft. "1/16S, BT"
	Elm 4 N29°W (mag.) 21.7 ft. "1/16S, BT"
	Elm 7 S63°E (mag.) 32.8 ft. "1/16S, BT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY *Arthur O. Enger* DATE **March 29, 1973**

Michigan Department of Natural Resources

13581

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

Form No. MLM736
DOUBLEDAY BROS. & CO. INC. ANN ARBOR, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS