

RECORDED

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

1999 NOV 29 AM 10:31

For corners in

Dickinson

Located In:

Corner Code #

(County)

Breitung Twp.

1. Public Land Survey

T 40NR 30WE-6T RD-5T RT RT R2. Property Controlling  
in SectionST RST RSURVEY 83. Miscellaneous  
Property in Sec.ST RST RREMONUMENTATION

MAR 24 2000

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

SECTION

I, Robert F. Perkins, in a field survey on March 9, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

Register of Deeds Stamp &amp; File Number

## A. Description of original monument and accessories and/or subsequent restoration:

E-6 East  $\frac{1}{4}$  Corner, Section 17  
 Post by J.H. Mullett, D.S. 1849  
 Original Bearing Trees  
 Aspen 12" S36°E 15 Lks.  
 Aspen 12" N14°W 18 Lks.

D-5  $\frac{1}{4}$  Corner 8 Section 17  
 Post by J.H. Mullett, D.S. 1849  
 Original Bearing Trees  
 Aspen 4" N74°W 07 Lks.  
 Aspen 4" S35°E 09 Lks.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-6 No Evidence of Original Corner Found.  
 Corner research under Contract #2, 1998  
 Found 2" Sq. Headed Bolt at Old Fence  
 Intersection  $\pm$  2619' South of N.E. Corner,  
 Section 17. Corner indicated on 1934  
 D.C.R.C. Map File A-10, No. 36, Sheet #3.

D-5 No Evidence of Original Corner  
 or Accessories Found.  
 Found Sq. Iron Bolt  $\pm$  1' below Road  
 Surface as shown on Dickinson Co.  
 R.O.W. Map File A-10, No. 36, Sheet 3.  
 Corner used and accepted on prior  
 Surveys.

ACCEPTED BY THE DICKINSON COUNTY  
 SURVEY PLER GROUP AS THE OFFICIAL  
 CORNER UNDER MICHIGAN PUBLIC ACT  
 305 JAN 1990 AT A MEETING HELD ON  
 11-23-99

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-6 Accepted Bolt described in E-6 above as  
 Best Remaining Evidence of Corner  
 Location. Replaced Bolt with 2 $\frac{1}{2}$ " Stamped  
 Cap, D.C. Remon. Marker.  
 New Witnesses  
 Ironwood 3" S32°W (M.B.) 22.79'  
 Ironwood 5" N45°W (M.B.) 15.48'  
 Ironwood 4" N59°E (M.B.) 42.88'  
 Maple 3" S79°E (M.B.) 36.66'  
 Placed Carsonite Marker North 0.85'

D-5 Accepted Bolt described in E-6 above  
 as Best Remaining Evidence of Corner  
 Location. Set 2 $\frac{1}{2}$ " Stamped D.C. Remon.  
 Marker over Bolt, in Monument Box.  
 New Witnesses  
 Maple 8" S45°W (M.B.) 106.65' Spike/Tag  
 R. Pine 14" N41°W (M.B.) 135.25' Spike/Tag  
 P. Pole #79-27988 N50°E (M.B.) 49.11' "  
 X Cut Top 4' Boulder S45°E (M.B.) 59.25' "  
 Corner is 14.6' East  $\frac{1}{2}$  Co. Road & 11.6'  
 South  $\frac{1}{2}$  Collins Rd.

Signed by Robert F. PerkinsDate Nov. 5, 1999Surveyor's Michigan License No. 12027

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN. 1983

REVISED OCT., 1985

LIBER 2

PAGE 474