

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Dickinson

(County)

Located In:

Corner Code #

1. Public Land Survey

T 41N R 28W C13

T R

T R

T R

T R

2. Property Controlling in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Jan 24 2001

I, Stephan J. Szyszkoski, in a field survey on _____, 19____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:
(C13) Standard Section corner on the 4th Correction Line between Sections 31 and 32. Recorded by Billy D. Buckler in 1954: "This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. Corner had been previously located and perpetuated by unknown surveyor. No original B.T.'s evident, but measurements check good in all directions. Corner was placed and witnessed July 20, 1954. 1" pipe with 4" brass cap. 6" Elm N26E 13 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C13) Recovered a 1.25" ID iron pipe, set firm, with adjacent leaning 1" pipe with 4" brass Michigan Dept. of Conservation cap - the 1954 monument of record. Accepted the position of the 1.25" dia. iron pipe as that of record. The remains of the 1954 Elm NBT, now a 1' high stub, are record bearing and distance from the 1.25" ID pipe. Left the monument in place and marked new accessories.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C13) 1.25" ID iron pipe and 1" ID iron pipe/4" brass cap adjacent. Blazed and scribed:


7" W. Spruce N52E 25.4' "S32 NBT"

5" Sugar S79E 9.5' "S2 NBT"

4" Sugar S30W 16.9' "S2 NBT"

4" B. Ash S86W 13.9' "S2 NBT"

Squared spruce post adjacent. Bearings are magnetic. Distances to notch in lower blaze.



Signed by

Stephan J. Szyszkoski

Date

1/25/2001

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources - Forest Management Division