

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

also T41N-R28W A06
For corners in

Dickinson Located In: Corner Code #
NORWAY TOWNSHIP
1. Public Land Survey
2. Property Controlling in Section
3. Miscellaneous Property in Sec.
4. Lot No. , Recorded Plat
5. Private Claims

2/14/2013AD
2/19/2013AD
Jeremy J. Pipp, in a field survey on do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(K06) Quarter corner common to Sections 13 and 14. 1849: John Burt, DS. Set Cedar post
witnessed by: Cedar 24 N47W 12 links (7.92'); Cedar 30 S32E 18 links (11.88'); 1959: Michigan
DNR (Billy Buckler PS#8887) Set 1" pipe with 4" Brass cap witnessed by 24" Y. Pine Stub S56W 43
links (28.38'), 7" Balsam N27W 69 links (45.54'). 1993: Ewart Muller (PS#15408) found MDNR
monument and witnessed : Spruce 5 N78E 14.35', Spruce 8 N88W 44.83', Spruce 10 S74W 48.60 & B.
Ash 3 N48W 7.53' .

(M06) Quarter corner common to Sections 13 and 18. 1846: William, John, & Austin
Burt, DS. Set Sugar post witnessed by: Hemlock 20 N45 1/2W 16 links (10.56');
Hemlock 18 S53 1/2E 45 links (29.70'); 1977: Michigan DNR (Arthur Enger PS#13581) Set
1" pipe with 3 3/4" Aluminum cap witnessed by Sugar Maple 11 S65W 27.3', Sugar Maple 6
N74E 29.0'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K06) Accepted found MDNR Monument and Three existing NBT Witnesses. Left MDNR monument
in place (replaced Broken cap) and rewitnessed. Accepted found MDNR Monument and
Witness remains as a careful and faithful REESTABLISHMENT of the position of the
original corner.

(M06) Accepted found MDNR Monument and Two existing NBT Witnesses. Left MDNR monument
in place and rewitnessed. Accepted found MDNR Monument and Witness remains as a careful
and faithful REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K06) DNR monument
4" Cherry S06W 46.28' (1/4S,NBT)
3" Cherry S68W 39.09' (1/4S,NBT)
EX. 4" Ironwood N51W 7.35' (1/4S,NBT)
4" Ironwood N32W 28.11' (1/4S,NBT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic. A
Carsonite rail was set North 1.5 feet.
(M06) DNR monument
8" Maple N68E 24.06' (1/4S,NBT)
10" ASH S68E 35.84' (1/4S,NBT)
EX. 15" Maple S67W 27.55' (1/4S,NBT)
12" Maple N30W 24.95' (1/4S,NBT)
All trees are blazed, scribed, and
painted. Measurements are to nail in
side of tree, bearings are magnetic. A
Carsonite rail was set North 1.5 feet.

Signed by Jeremy J. Pipp Date July 22, 2013
Surveyor's Michigan License No. 50447

For the Michigan Department of Natural Resources, Forest Resources Division

