

RECORDED

1998 DEC 14 PM 12:26

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Dickinson

Located In:

Corner Code #

(County)
Norway Twp.

1. Public Land Survey

T 41 N R 29 W

B-7

T R

C-7

T R T R 2. Property Controlling
in SectionS T R 3. Miscellaneous
Property in Sec.S T R S T R 4. Lot No. , Recorded Plat 5. Private Claims

SECTION

I, Robert F. Perkins, in a field survey on Nov. 4, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-7 $\frac{1}{2}$ Corner Common to Sections 18
Y. Pine $\frac{1}{2}$ Post by John Burt, D.S. 1849
Original Bearing Trees
W. Birch 8" S20°E 10 Lk.
W. Pine 10" N9°W 15 Lk.

C-7 Southeast Corner, Section 18
Post by John Burt, D.S. Oct. 10, 1849
Original Bearing Trees
W. Pine 10" S75°W 12"
W. Pine 10" N70°E 15"

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-7 No Evidence of Original Corner
or Accessories Found.
Found remains of Damaged 1" Iron Pipe
D.N.R. Marker set by Billy Buckler, RLS
in 1962 (Old Corner Report #648)
1962 Bearing Trees:
W. Birch 8" N4°E 60½ Lk.
Aspen 5" N62°E 08 Lk.

C-7 No Evidence of Original Corner
or Accessories Found.
Found 1" D.N.R. Pipe Monument with 4"
Brass Cap set by Billy D. Buckler, RLS
in 1962. (Old Corner Report #649)
1962 Bearing Trees:
Red Oak 12" S44°E 20½ Lk. (Found)
Red Maple 6" S77°E 49 Lk.
Jack Pine 8" N56°W 55 Lk.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-7 Accepted Damaged Pipe Marker described
in "B" above and Replaced same with 2½"
Stamped D.C. Remon. Corner.
New Witnesses:
W. Pine 14" N05°W(M.B.) 46.30' Nail/Tag
W. Pine 10" N70°E(M.B.) 60.00' Nail/Tag
N. Pine 13" S20°W(M.B.) 17.85' Nail/Tag
N. Pine 13" N70°W(M.B.) 26.05' Nail/Tag
Placed Carsonite Marker at Corner.

C-7 Accepted Pipe Marker described in
"B" above.
New Witnesses:
Oak 20" S44°E(M.B.) 14.10' Nail/Tag
Oak 8" N88°E(M.B.) 33.20' Nail/Tag
Oak 3" N10°W(M.B.) 44.50' Nail/Tag
R. Pine 12" N38°E(M.B.) 129.70' Nail/Tag
Placed Carsonite Marker 1.0' North.

Signed by

Robert F. PerkinsSurveyor's Michigan License No. 12027

ACCEPTED BY THE DICKINSON COUNTY

SURVEY PEER GROUP AS THE OFFICIAL

CORNER UNDER MICHIGAN PUBLIC ACT

345 OF 1990 AT A MEETING HELD ON

12-7-98

COUNTY REPRESENTATIVE

Date Nov. 20, 1998

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1985

Liber 2 Page 401