

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

1998 DEC 14 PM 12:24

For corners in

Dickinson

Located In:

Corner Code #

Norway Twp. (County)

1. Public Land Survey

T 41NR 29W

D-7

T R

D-9

T R

T R

T R

2. Property Controlling  
in Section

S

T R

S

T R

3. Miscellaneous  
Property in Sec.

S

T R

S

T R

SECTION

REGISTER OF DEEDS  
DICKINSON COUNTY  
RON MOUNTAIN, CLERK

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Robert F. Perkins, in a field survey on Nov. 4, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

D-7  $\frac{1}{2}$  Corner Common to Sections 20  
Post by John Burt, D.S. 10-2-1849  
Original Bearing Trees  
W. Birch 10" N65°E 35 Lk.  
W. Birch 8" S50°W 28 Lk.

D-9  $\frac{1}{2}$  Corner Common to Sections 20  
Post by John Burt, D.S. 10-8-1849  
Original Bearing Trees  
Hemlock 16" N22°E(M.B.) 11 Lk.  
Hemlock 18" S37°W(M.B.) 13 Lk.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-7 No Evidence of Original Corner  
or its Accessories Found.  
Found 1" D.N.R. Pipe Marker with  
4" Brass Cap set by Billy D. Buckler,  
RLS 5-1-1961 (Old Corner Report #631)  
1961 Bearing Trees:  
J. Pine 9" S19°W 52 Lk.  
W. Pine 8" N79°W 32 $\frac{1}{2}$  Lk. (Found)

D-9 No Evidence of Original Corner  
or its Accessories Found.  
Found 1" Pipe D.N.R. Marker with  
4" Brass Cap set by Billy D. Buckler,  
RLS in 1960. (Old Corner Report #416).  
1960 Bearing Trees:  
Maple 8" N78°W 52 Lk. (Found)  
Maple 6" N30°E 28 Lk.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-7 Found and Accepted Pipe Marker  
described in "B" above.  
New Witnesses:  
Oak 6" S75°W(M.B.) 11.33' Nail/Tag  
S. Maple 10" S88°E(M.B.) 38.55' Nail/Tag  
Fir 6" N08°W(M.B.) 12.45' Nail/Tag  
R. Maple 3" S18°W(M.B.) 26.68' Nail/Tag  
W. Pine 14" N79°W(M.B.) 1962 B.T.  
Placed Carsonite Marker 1.0' North.

D-7 Found and Accepted Pipe Marker  
described in "B" above.  
New Witnesses:  
Maple 4" S87°E(M.B.) 10.68' Nail/Tag  
Maple 12" N78°W(M.B.) 34.53' Nail/Tag  
Maple 3" N23°E(M.B.) 15.15' Nail/Tag  
W. Birch 14" S23°W(M.B.) 14.95' Nail/Tag  
Rock Bluff South  $\pm$ 50'  
Placed Carsonite Marker 0.80' West.


Signed by Robert F. Perkins  
Surveyor's Michigan License No. 12027

Date Nov. 20, 1998

ACCEPTED BY THE DICKINSON COUNTY  
SURVEY PEER GROUP AS THE OFFICIAL  
CORNER UNDER MICHIGAN PUBLIC ACT  
345 OF 1990 AT A MEETING HELD ON

12-7-98

COUNTY REPRESENTATIVE



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1985

Liber 2 Page 403