

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson Located In: Corner Code #
(County)
FELCH TOWNSHIP
1. Public Land Survey T 42N R 29W B03
T 42N R 29W C04
2. Property Controlling S T R
in Section S T R
S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

2/25/2013AD
1, Jeremy J. Pipp, in a field survey on 2/25/2013AD do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(B05) Quarter corner common to Sections 6 and 7. 1849: John Burt, DS. Set Sugar post
witnessed by: Sugar 14 S39W 11 links (7.26'); Sugar 18 N60E 46 links (30.36'); 1965:
Michigan DNR (Frank Bray PS#13575) Set 1" pipe with 4" Aluminum cap witnessed by 18"
Hard Maple S06W 69 links (45.54'), 5" S. Maple N82E 42 1/2 links (28.05').

(C04) Quarter corner common to Sections 7 and 8. 1849: John Burt, DS. Set Cedar post
witnessed by: Lynn 16 N37W 25 links (16.50'); Y. Birch 16 S44E 58 links (38.28');
1965: Michigan DNR (Frank Bray PS#13575) Set 1" pipe with 4" Aluminum cap witnessed by
10" Ironwood N81W 59 links (38.94'), 11" Ironwood S20W 82 links (54.12').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(B03) Accepted found MDNR Monument and One existing NBT Witnesses. Left MDNR monument
in place and rewitnessed. Accepted found MDNR Monument and Witness remains as a careful
and faithful REESTABLISHMENT of the position of the original corner.

(C04) Accepted found MDNR Monument as a careful and faithful REESTABLISHMENT of the
position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Table with 2 columns: (B03) DNR monument and (C04) DNR monument. Rows include measurements for 5" Maple, 4" Ironwood, 7" Maple, and EX. 8" Maple, along with descriptions of trees and measurements.

Signed by Surveyor's Michigan License No. 50447 Date July 22, 2013