

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson (County) Located In: Corner Code #
1. Public Land Survey T 42N R 29W B05
T 42N R 29W C03
2. Property Controlling S T R
in Section S T R
S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) containing numbers 1-36 for the Register of Deeds Stamp.

2/20/2013AD
2/25/2013AD
Jeremy J. Pipp, in a field survey on do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(B05) Quarter corner common to Sections 7 and 18. 1849: John Burt, DS. Set Sugar
post witnessed by: Sugar 10 N48E 36 links (23.76'); Y. Birch 12 S60W 11 links
(7.26'); 1965: Michigan DNR (Frank Bray PS#13575) Set 1" pipe with 4" Aluminum cap
witnessed by 5" Hard Maple N10W 25 1/2 links (16.83'), 11" Aspen S05E 08 links (5.28').

(C03) Corner common to Sections 5, 6, 7, and 8. 1849: John Burt, DS. Set Sugar post
witnessed by: Sugar 14 N55W 46 links (30.36'); Hemlock 14 S81E 33 links (21.78');
1965: Michigan DNR (Frank Bray PS#13575) Set 1" pipe with 4" Aluminum cap witnessed by
8" Aspen N69W 28 1/2 links (18.81'), 7" Aspen N76E 10 1/2 links (6.93').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(B05) Accepted found MDNR Monument, left in place and rewitnessed. Accepted found MDNR
Monument and Witness remains as a careful and faithful REESTABLISHMENT of the position
of the original corner.

(C03) Accepted found MDNR Monument and Two existing NBT Witnesses (both dead). Left
MDNR monument in place and rewitnessed. Accepted found MDNR Monument and Witness
remains as a careful and faithful REESTABLISHMENT of the position of the original
corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B05) DNR monument (C03) DNR monument
4" Poplar N69E 22.39' (1/4S,NBT) 5" Maple N31E 28.16' (S5,NBT)
5" Poplar S50E 4.92' (1/4S,NBT) 10" Maple S33E 11.65' (S8,NBT)
3" Maple(clump) S54W 48.61' (1/4S,NBT) 5" Maple S85W 6.22' (S7,NBT)
EX 11" Maple N04W 16.90' (1/4S,NBT) 10" Maple N54W 41.97' (S6,NBT)
All trees are blazed, scribed, and painted. Measurements are to nail in
side of tree, bearings are magnetic. A Carsonite rail was set North 1.5 feet.
All trees are blazed, scribed, painted, and signed. Measurements are to nail in
side of tree, bearings are magnetic. A Carsonite rail was set North 1.5 feet.

Signed by [Signature] Date July 22, 2013
Surveyor's Michigan License No. 50447

