

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Dickinson

(County)

Located In:

Corner Code #

1. Public Land Survey

T 43N R 28W

67

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

May 29 2001

I, Stephan J. Szyszkoski, in a field survey on _____, 19____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	16		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

(67) Corner common to Sections 15-16-21-22. Remonumented in the original position from the original cedar bearing trees by Henry S. Peterson RLS, in 1957. 1" Pipe with 4" brass cap. Cedar 13" N81E 26 links, W.Birch 10" S81W 25 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(67) Recovered the 1957 monument as described, in good condition, and at record bearing and distance from the 1957 witness trees, both decaying stumps with scribing visible. Left the monument in place and made new witnesses. No sign of the original cedar BTs.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(67) Found 1" ID iron pipe with 4" brass

MDOC cap. Blazed and scribed:

17" Cedar N08E 47.0' "S15 NBT"

15" Cedar N86E 41.0' "S15 NBT"

12" Cedar S19E 65.3' "S22 NBT"

10" Spruce S37W 54.3' "S21 NBT"

Sq'd cedar post adjacent. Bearings are magnetic. Distances are to notch in lower blaze.



Signed by

Surveyor's Michigan License No.

Date

For the Michigan Department of Natural Resources - Forest Management Division