LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	Pickinson	Located In:	Corner Code ≠≠	1										
	(County)		Coules Code 111	ļ										
1.	Public Land Survey	T <u>4411</u> R <u>280</u> T R T R												
2.	Property Controlling in Section	S T R												
3.	Miscellaneous Property in Sec.			Re	piste	of	Dec	ds S	itamı	o & F	ile (Num	ber	
4.	Lot No.	Recorded Plat							,		•			
5.	Private Claims		-		4		<u>c</u>	0	E F	G	H (J	K	
					2	_ [.	┸	LЦ	LI.			_Ţ	\perp	Ţ
		•			a	Ľ	1	Ĭ	Ξĭ	Ti	iΠ	_i	Т	ï
					4	Ţ	Т		П		П	\neg	7	7
L _	Stephen J. Szyszkoski	, in a field survey onRUG	wst 01, 1994 19			- i	T	i		7-7	•	—11- 1	1	-12
00	necedy certify that minder ri	equirements of P.A. 74. Michigan P.A	of 1970, the corner points men	icand	Ţ.	7	1			11	┌┪	+	╈	+-
in I	ines 1 and 2 above were	in conformance with regulations as	nd rules therefore as required	in the	"	-1 0 -	+	ľΉ	⊢ ;•-	┼ ~?	5 →	-14-	┿	·13—
Ma Ma	reth menual of survey insi Nacement of by a decree o	tructions of the United States Depart I a Court of Law and/or that the com	riment of the Interior, Bureau of	Land	" }	╅	┰	╂╌┨	+	╆┤	\dashv	┯┼-	╁	┿
e Do	we were in conformance w	rith the rules of the Michigan Board :	of Land Surveyors or by a Decre	na of a	•⊦	-13-	┿	;ͽ᠆ϯ	—s¦ı-		2-		┿	4-
CO	#1 of Law; established,	re-established, monumented, re-	monumented, recovered, four	nd as	•	╁	+	┦	-	₩	┵	+	╀	╄
	ressed below:				16	-36-	┵	,	_ _	1-2	ᆛ	_d-	4_	<u></u>
NQ	TE: Not more than 4: on this certificate	corners, all in the same town a	nd range, may be recorded		"-	+	╁	H	+	╁┼	\dashv	+	+	•
	and Shallfill	•			"* -	-31-	╁	╬╌┤	—\$ } -	┼╬	↤		╁	*-
A.	Description of original	monument and accessories an	d/or subsequent restoration		13 L			щ		4	_			ш
400	A1 A													

(K18) Buarter corner common to Sections 25-36. Corner recorded in 1954 by Dean C. DelaNater, set by proportionate measurement. 1" pipe with 4° brass cap. Mitnessed by 30° Boulder \$36£ 100 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(KIO) Found the measurent placed in 1953 by DetaMater, a 1° I.D. iron pipe with 4° brass Michigan Dept. of Conservation tablet, in good condition, apparently undisturbed, 67' mest of the conterline of a county road. The boulder mitness was found \$31E, 48.3' (to top) from the monument. I suspect that the boulder, being in a ditch, was moved since the 1954 recordation. Left the monument in place and marked 3 new witnesses as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K10) Found 1" pipe with 4" brass cap. Blazed and scribed the following new bearing trees: 12" Spruce M66# 26.8" "1/45 NBT" 8" Spruce S61H 27.8" 1/45 MBT A wood fance corner post with fencing mest bears \$56E 96' The boulder noted in the 1954 record is \$31E 48.3' to its top. Bearings are. magnetic.

STEPHAN J. SZYSZKOSKI LAND SURVEYOR

Signed by Stychen

Surveyor's Michigan License No. _

33986

For the Michigan Department of Matural Resources - Forest Management Division. **REVIESD MAY 14, 1976**