

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 44N R 30W	E9
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 07/29/2010 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E9) Corner common to Sections 20-21-28-29. 1848 - Established by John Burt Deputy Surveyor. Set Spruce post. W.Pine 20 S55W 40 links, Spruce 18 N59E 37 links. 1934 field book notes of E.R.Nelson and W.C.Johnson on file at Dickinson Co. Rd. Commission office show "found 4" square spruce stake for Section corner and old line trees to the West and South. We set New BTs...": 6" Birch N25E 33.8', 10" crooked Spruce N40E 14.1', 4" Tamarack N79E 50.5', 6" double Spruce S76W 56.9'. Corner shown on a 1941 drawing by Holland, Ackerman, and Holland for Wisconsin Michigan Power Co., Way Dam Reservoir: 1.5" iron pipe set by County. Replaced with concrete monument. 2" Spruce N82W 7.7', 14" Spruce N38E 14.2', 3" Spruce S52W 18.5'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E9) Found a Wisconsin Michigan Power Company concrete monument, 7" square, with raised square brass tablet, stamped to identify the corner, in good condition, and at record bearing and distance from what is taken to be the remains of the WMPCO 14" Spruce NBT N38E 14.5' (also being the 1934 10" crooked Spruce), now a dead stub 24" DBH with a rotted overgrown blaze and possible scribing visible, facing the monument. Accepted the monument as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E9) Found 7" square Wisconsin Michigan Power Company concrete monument.
Set measuring nail with MDNR tag in the side of:
10" W.Spruce S77E 21.2' mrkd "S28 NBT"
6" B.Spruce S16E 38.9' do
15" W.Spruce N74W 7.8' "S20 NBT"
4" B.Spruce N14W 21.8' do
Fd. metal location poster on 15" W.Spruce, above.
Set sq'd cedar post adjacent.
Bearings are magnetic.



Signed by Stephan J. Szyszkoski Date 12/09/2010
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources and Environment, Forest Management Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971